Certificate of Location of Government Corner

ID#: 613405 **Description:** S SEC COR 33 34 61 **Date Set:** 6/22/1976 **County:** Olmsted

Section: 34 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in centerline of twp road east and 29' NE of centerline of CSAH 30 on curve
County Survey Disk in PP NW 130.1'
County highway disk in PP NE 60.2'
County Survey Disk in 15" Spruce SW 106.3'
County Survey Disk in 16" Maple SE 74.62'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor West between sections 3 and 34. 80.00 chs. Set post and drove charred stake for corner to sections 3,4,33 and 34. Built mound with trench per instructions. Planted S.E. plumb, N.E. apple seed

11-1891 Thomas Fraser (P. 462 No. 446), County Surveyor, found a large boulder with a stake by its side.

10-1897 William Fraser (P. 613 No. 557), County Surveyor, found corner P. 483.

1935 county highway department (B. 75 P. 7) found a flat limestone on top of a pile of rocks. Set a limestone with cross as the corner.

1943 county highway department (B. 180 P. 76) had corner B. 75 P. 7.

8-1961 county highway department (B. 240 P. 4) found stone monument. Set a C.I.M.

9-8-1975 County Surveyor dug at the location of a ½"x12" rod found in the blacktop road. Found a pile of stones 3' deep. Dug out the stones and found a black mark extending into clean clay. Set a 3/4"x24" shaft over the mark.

6-22-1976 County Surveyor accepted the location of the 3/4" shaft set 9-8-1975 as the corner. Removed the shaft and set a C.I.M. over a ½"x12" rod as the corner.

9-29-1998 County Surveyor found CIM in good condition 6" deep in bituminous road.

7-23-2003 County Surveyor found CIM down 0.6' in good condition.