Certificate of Location of Government Corner

ID#: 613506 **Description:** 1/4 SEC COR 34 35 61 **Date Set:** 11/23/1998 **County:** Olmsted

Section: 35 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.1'
The corner falls 1' south of E-W fence and between two large boulders east and west
Post w/sign 1' south
This corner is located by GPS measurement.

Corner History:

1853 Gov't Notes: J. Ball, Set 1/4 section corner post M&L 40 chs 2640' 6" Burr Oak N66W 233 lks 153.8. Corner now on E-W farm boundary line, common land on N7S sides of corner. Corner in highest land in area, level and wide contour.

11-1891 Thos Fraser (P.462 No.446) corner used in establishing NW cor 2 105-11 P.462 found iron by foot of post which is corner of fences N-E-W set by Olds and Keyes in former survey, claimed by Keyes as set exact point of original gov't stake, no meas S to sec cor.

8-19-1980 County Surveyor dug for iron by post used by T. Fraser in 1891 survey. Found stone 4" x 5" x 12" standing beside old post mark running well down into clay. Found rusty piece but no iron hole. Set bottom 1' of a steel fence post at the post location.

11-17-1998 GGG found and used steel post stub.

11-23-1998 County Surveyor found steel fence post bottom set in 1980 at post and stone location. Set Cast Iron Cap on telspar pipe at this location.

2-8-2011 County survey crew found cast iron cap on telspar pipe in good condition.