Certificate of Location of Government Corner

ID#: 620305 **Description:** SEC COR 3 4 9 10 62 **Date Set:** 8/12/1969 **County:** Olmsted

Section: 03 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in centerline of twp road south and 2' south of centerline of E-W twp road
Mag nail in top of west end 15" CMP - N 7°36’ E 26.36’
Nail & Bottle Cap in PP - S 56°33’ E 51.75'
Nail & Bottle Cap in PP - S 55°10 W 50.10'
This corner is located by GPS measurement

Corner History:

Set by William Jones 9-1853 80.00 Set post at Corner to sect 3, 4, 9, & 10. Deposited handful white flint, made mount, trench, & pits planted cherry seeds SW & NE.

10-1872 Hunter P. 209 No. 217 found stone set as sec. Corner. Measured east 39.99 to stake found. 1/16 south set stake M & L 20.02 to stake found.

5-1903 Armstrong P. 46 B found stake with stones & brick around it. Drove new oak stake. Set stakes west for property corner. 1/16 W 19.91 1/2 (1314.4)then 11.70 1/2 (772.53) then 8.21 (541.86) to 1/4 cor. Measured North 39.89 (2632.74) to 1/4 cor a fence corner).

8-12-69 J. Kerr found 1" x 18" iron bar no references. Old road down 20" undisturbed - figured corner assumed. Dug out 2nd road probed and found stone 1.35'N and .5' W of iron. Set CIM over original stone and bricks found some junk. Pepsi cap on NE side power pole #434 SE 51.75. Mountain Dew cap on NW side brace only pole #435 SW 50.1 Center top square telephone calbe control post NE 39.95. Measured west to help locate SW corner 4 dnd test fence S at S1/4. Total to center crossroads 2631.3. Found fences north at 2056.5 - 124.63 rods - 125 acres by deed. Found fences north at 3046.0 - or 989.5' 59.95 rods 60 acres by deed. Found fences north at 3703.0 or 657.0', 39.82 rods 40 acres by deed. Balance fences north at 3703.0 or 1567.0' 94.97 rods 95 acres by deed.

3-24-72 County Surveyor measured east to plug 2.75'E of Centerline 42 2635.05. Measured south 5279.5 CIM to CIM at 9-10-15-16. Found 1/16 fence E at 1324.5 then 1316.8 to corner post set.)

C.A. Field Bk #4 from A.A. Books P. 113 Survey Sec 4. Quote: from Cor. Of 3-4-9-10 which is a stone witnessed, by A B1 O.Tree 10 S77W 2'3", I run N 26655 1/2' to Cor., 5261' intersect N. Bdy 40' W. of Corner of Sec. 3-4-33-34 which is a Limestone 6 x 6 (something I can't read) and in South wheel track - from Cor. Of Sec. 3-4-33-34 run W. 2644' find 1/4 stone in N. wheel track and line of fence So. - 26'4" N of Cor. Post

6-12-2001 County Surveyor found CIM down 1.0' inside 8" PVC w/cap in good condition.

6-11-2002 County Surveyor found CIM inside 8" PVC w/cap in good condition.

10-28-2013 MnDOT Survey Crew found CIM in good condition.

05-19-2014 MnDOT Survey Crew checked for & updated existing ties. Set 1 new tie: Mag Nail in top of west end 15” CMP in field approach - N 7°36’ E 26.36’