Certificate of Location of Government Corner

ID#: 620404 **Description:** 1/4 SEC COR 4 9 62 **Date Set:** 7/16/2003 **County:** Olmsted

Section: 04 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 22' south of centerline of E-W twp road, in centerline of field entrance south and 2' west of fence south
Concrete nail in W side PP #15938 S 13.6'
This corner is located by GPS measurement

Corner History:

9-1853 Set by William Jones. 40.04 Set post at gr. Sec. Corner deposited handful of charcoal made mound pits & trench & planted cherry seeds NE & SW.

5-1903 C. Armstrong P. 46 B. S 4 A Randall etal found old cedar stake claimed to be true corner. It lies some 40 links (26.4') south of straight line between section corners on line between Secs 4 & 9. Set stakes for prop corners east and west. East 8.20 1/2 then 11.70 1/2 for 1/16 corner then 19.91 1/2 Sector. West 6.20' then 9.97' then 2370 to Sec. Corner. (In cases of both here and at center it looks like 8.20 is 9.20'.)

8-12-1969 J. Kerr. Meas from CIM at 3-4-9-10 West. Found property line fence running north at 1326 R 1314.4, no true line; found property line fence running north at 2056.5, R 2086.78, 2090.53; found property line fence runing south at 2631.3', R2628.78, 2633.33'; found property line fence runing north at 3703.0', R 3696.0, 3043.26'; found property line fence running north at 3046.0', R3038.0, 3703.39'; found center crossroads N-W-S-E at 5270.0', R5260.2, 5269.30'. Total 1/2 miles 7902.7, R7889.0 or .173' per 100' results in green at 1/4 4-9. If eye line fence S is 2631.3' and true porportion is 2633.33' then corner should be 2' West of fence S - no line run

8-27-1973 County Surveyor offset 40 lks (26.4' south at 4-5-8-9 and 3-4-9-10 and set referenced point in line fence south at 1/4 4 - 9. Point fell 20' south center road in ditch area which was field drive area for farms both east and west of new fence running south. Dug entire area nearly 2'. New crushed rock over both drives. Found definite wood stake, practically no length left, in some dark soil dug area. Drove 1 1/4 x 3' poipe into center stake location on almost exact line set up 26.4' south direct line of CIM S of seection corners. Meas E to CIM 30-4-9-10 2633.3'± R2628.8; Measure W to CIM 4-5-8-9 2635.1'±, R2631.4; Measure 4-5-8-9 to 1/4 58 CIM 2638.3'± R2628.8. Note that Chas Armstrong measured to fence North at 1/4 5-8 which now is over 4' West. RPS 1/4 4-9 Eyota 1 1/4 x 3' pipe. 57.25' 4' E of N to wires sticking out of center west side large 24" ash or maple tree. 13.6' Due S. to concrete nail W side PP 15938.

6-12-2001 County Surveyor found 1 1/4" pipe down 1.1' in good condtion.

7-16-2003 County Surveyor found 1 1/4" pipe down 1.0'. Took local ties and removed. Set CIC on a 5.0' telspar pipe down 0.5'.

4-20-2009 County Surveyor found cast iron cap on telspar pipe down 0.5' in good condition.