Certificate of Location of Government Corner

ID#: 620805 **Description:** SEC COR 7 8 17 18 62 **Date Set:** 4/4/1977 **County:** Olmsted

Section: 08 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls on shoulder, 7' south of centerline of twp road east and 7' west of centerline of twp road south
County Survey Disk in N side PP #42544 ESE 108.70'
County Survey Disk in W side PP #42484 SSW 132.80'
County Survey Disk in S side CP W 30.43'
Post w/sign 1' West
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor
North between sections 17 and 18. 80.00 chs. Set a post at the corner to sections 7, 8, 17 & 18. Burr Oak 8" N89°E 40 lks. Red Oak 6" N10°W 19 lks. Burr Oak 5" S45°W 46 lks. Burr Oak 7" S15°E 64 lks.

5-1877 Thomas Hunter, County Surveyor, (P. 310 No. 304) found a "pole" avered by a Mr. Cassidy and others as the corner. Accepted this as the corner and set a stake.

5-7-1883 T.H. (Fieldbook 14, P. 3) measured 79.86 from SE 18 to line of board fence running West at NE 19. NE 18 missing they having plowed and scraped the road and totally destroyed all evidence of it.)

6-1893 William Fraser, County Surveyor, (P. 512 No. 480) found the corner P. 310. Drove an iron stake as the corner which lines with the fence West. (from card: drove stake 80 rods south; drove stake 35 rods south of above state; measured south to 1/4 corner stone set M & L 39.83)

10-1930 John Kerr, County Surveyor, (B.4 P.10) found an iron in line with the fence West (from cards: only copying W.F. here but he did use something. Measured south to E 1/4 18 2626.29 rough line. 10" blazed oak N 38° E 58.5' blazed at root and 5' up. 12" blazed oak N 70° W 51.2.)

8-7-1968 John Kerr found a square bridge bolt as the corner in a dug pit 18" deep. (from cards: Did not set CIM at this time. Found square bridge bolt as corner in dug pit 18" deep. 10" burr oak Nov 18" 58.2' to nail in blaze (head of nail) N 38°E. Center of number plate 15881 on power pole NW 81.8' this measure knee high at corner to plate on direct clope. Head of nail in tall corner post of fence west which is in line with corner as the fence runs West - W - 30.4'. Disc on E side power pole No. 15880, badly shot up SSW 131.55'.)

5-11-1970 County Surveyor found a 1 1/2" square headed bolt. Set a C.I.M. over the bolt.

4-4-1977 County Surveyor found the C.I.M. set in 1970. Set a C.I.M. over it and up to the surface. (from cards: Set a CIM over the CIM in place. Corner on East bank of ditch on West side of turnaround at the intersection of roads East and South. Corner 7' West of centerline road So. And 7' So of centerline road East and in line with the fence West) R.P's C.S.D. N. Side PP #42544 ESE 108.70 CSD W Side PP #42484 SSW 132.80;' CSD S side corner post to fence S-W-N W 30.43'.

7-30-2001 County Surveyor found CIM down 0.4' in good condition.