Certificate of Location of Government Corner

ID#: 620905 **Description:** SEC COR 8 9 16 17 62 **Date Set:** 4/15/2009 **County:** Olmsted

Section: 09 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 4' south of centerline of E-W twp road and in centerline of CR 102
Punch hole in N end 18" CMP NE 34.95'
Punch hole in S end 18" CMP SE 31.90'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes North between sections 16 and 17. 80.00 chs. Set section corner post. Burr Oak 4 in. N26° W 353 lks. Burr Oak 12 in. N14 1/2°W 106 lks. Burr Oak 15 in. S75°E 348 lks. Burr Oak 14 in. S2 1/2°W. 1000 lks.

5-1877 Thomas Hunter (P. 310 No. 304), County Surveyor, found stake in center of road claimed by old settler to be where original stake once stood. (from cards: B tress gone. North set stake on line E 1/4 S and midway and south side railroad lands. 12.28 3/4 M & L 811.0'; aldo set stake on line E 1/4 S and midway from E 1/4 S and northside RR lands 6.93 1/2 M & L 457.7.)

8-1898 William Fraser (P. 640 No. 576), County Surveyor, found large boulder on top of old stake. (from cards: measured east 39.95' to small stake set M & L 2636.7; measured south 39.94' to stone reset in wooden culvert 2636.04)

5-1902 Charles Armstrong (P. 46 Book B), County Surveyor, found stake and stone.

8-7-1969 J. Kerr measured from rod set at 16-17-20-21 (to tie measure from east) North apparently did not adjust measure to measure from center crossroads at SW 16. May indicate corner there lies north of center where set iron in center crossroads at NW 16 5265.0'. Center power pole SE 48.0'; Center 28" oak NE 47.7'.

8-3-1973 County Surveyor found recorded 16" x 18" x 30" boulder with 2 1/2 x 24" stake well preserved below stone driven deep into very wet subsoil. Drove a 1 1/4" x 36" pipe in place of stake and placed large stone NW of the pipe. (from cards: Dug with tractor, found over 2' of very hard fill then sticky black muck for 2' then gooky clay. Found 16" x 18" x 30" boulder with 2 1/2 x 24" oak stake drive well into clay. Removed stake and drove 1 1/4" x 36" pipe into hole. Dumped huge stone NW of pipe with one other stone 14" dia or so with it. Did not set anything afer filling hole. Referenced carefully. 44.6' SE to conc nail in the tele pole NES; 77.25' NE to conc nail in tele pole SES; corner 3.3' south 1.6' east of road set 8-19-68)

8-29-1973 County Surveyor set CIM over pipe 2 new ties. 31.83' Sely to single punch hole in top center S end 18" culv.; 34.84' NE to same N end. Could not find 1/4 16-17 so reset from line from E temporarily. Will change slightly to fit all corner concerned.

7-30-2001 County Surveyor found CIM down 1.2' in good condition.

4-15-2009 County Surveyor found CIM w/o head down 1.3' in good condition. Removed CIM and found 1 1/4" pipe down 3.9' in good condition. Set 3.4' telspar pipe w/Cast Iron Cap down 0.5' at CIM positioin.