Certificate of Location of Government Corner

ID#: 621005 **Description:** SEC COR 9 10 16 15 16 62 **Date Set:** 7/13/1971 **County:** Olmsted

Section: 10 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2' west of centerline of N-S twp road and 1' south of centerline of twp road west
120d spike in center of road down 2" S 1°14' E 92.6'
Concrete nail in NE side PP #486 - N 37° 51' W 56.45'
PK Nail in SE face of utility guard post - S 41°24' W 44.10'
This corner is located by GPS measurement

Corner History:

1872 Hunter (Bk A. Pg. 209) found the stake in the center of the road. (from cards: measured east 39.97 1/2 to point set as 1/4 corner M & L south sec line 10. S 89° 55' E (268.35'); 1/16 north set stake M & L 20.00 N 35' E. line each; measured North 10.42 to RR (likely centerline) then 9.58 to W 1/4 10.

1898 W.Fraser (Bk A. Pg. 640) found the stone and stake.(from cards: P. 640 No. 576 S 16. Decay bearing. Found stone and stake as set and located by Hunter P. 209. Measure west 39.95' to small stake set M & L as that corner could not be found. S 89 1/2° E.)

8-1968 J. Kerr measured from rod set as tie rod in center crossroads at NW 16 east. Set rod as measured tie in center roads N-S-W at NE 16 at 5274.0. R. 5273.4 to stone set P. 209 1872. Center PP NW 51.3 Center telephone pole SW 67.4'.)

6-30-1971 County Surveyor 1 mile of road west must soon be graded. Figured could easily find recorded stone after so much initial work. Found 1/2" rod set 8-1968 and used. 5-1970 also found 1" iron near surface about 2' NE of 1/2" iron. Dug 2 1/2 x 4' to subsoil base covering all corners with 1/2" iron in North 1/3 of hole. Probed all directions. Opened small holes in road SE, SW, N and probed with 4' probe. Found nothing only small subsoil stones. Corner either gone or lies likely west of area, hard to tell. Filled hole and replaced small rod, large rod still in place.)

7-6-1971 County Surveyor dug entire road with Forrest Wharton Cat blade. Found stone 10x12x14 with definite signs stone had been placed as corner. No other stones in area. Set 120d as temporary corner.)l

7-13-1971 County Surveyor found boulder stone 10" x 12" x 14" and set permanent marker consisting of cast iron monument over the stone with glass. (from cards: Found 120d and local references. Set CIM resting directly on stone, trash, glass. Pulled both other iron corners. 92.6' S to 120d in center road down 2"; 39.9' SE to hard nail on NE side telephone pole up 3'; 56.45' WN to hard nail on NE side power pole #486. 120d in road has 1 RP hard nail W side telephone phone NENE 76.4'.

6-17-1999 W. Claassen found CIM in center "T" intersection down 12"

3-16-2005 Yaggy Colby Associates used CIM for survey in NW 1/4 sec. 15.

9-22-2006 Yaggy Colby Associates used CIM for large survey in section 10 and 15.

4-20-2009 County Surveyor found CIM down 1' in good condition.

10-24-2013 MnDOT Survey Crew found the Cast Iron Monument in good condition.

05-19-2014 MnDOT Survey Crew checked for & updated existing ties. Set 1 new tie: PK Nail in SE face of utility guard post - S 41°24' W 44.10