Certificate of Location of Government Corner

ID#: 621104 **Description:** 1/4 SEC COR 11 14 62 **Date Set:** 8/14/2018 **County:** Olmsted

Section: 11 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with centerline of CSAH 7 north and 1' south of centerline of twp road east
The monument is at the surface
Ref pipe E 309.70'
Post w/sign west 2'
This corner is located by GPS measurement

Corner History:

Set by William Jones 9-1853. 40.20 Set post at gr. sec. corner deposited handful gravel made mound trench and pits and planted cherry seeds NE & SW.

June, 1867 M.E. Herton Pg. 86 No. 132 shows 1/4 Cor (See survey for interior of Sec. 11).

9-1891 Thos Fraser P 454 No 438. Corner gone. Set stone 3 x 10 x 15 coming to point on top M & L 39.90 1/2 (2633.7)

6-30-1964 J. Kerr found railroad spike checked by references and set a permanent marker consisting of a Cast Iron Monument over 3/4" x 14" steel rod.

7-14-1975 County Surveyor dug down with backhoe for the recorded stone 3' - 7' west of CIM present location and 1 to 3' south but found no evidence of the stone.)

5-4-2000 County Survey Crew found CIM in good condition at surface. Set ref pipe and tied out corner.

12-11-2000 County Survey Crew set 120d spike at surface from 2000 tie out. Road regraded. Corner now falls in west ditch of CSAH 7.

8-31-2001 County Survey Crew found 120d spike set in December 2000. Set 5' long telspar pipe w/CIC as final corner up 0.3'

6-17-2002 County Survey Crew found cast iron cap on telspar pipe up 0.3' in good condition.

11-25-2003 MnDOT survey crew found monument in good condition.

8-23-2004 County Survey Crew found cast iron cap on telspar pipe up 0.3' in good condition.

3-20-2007 County Survey Crew found cast iron cap on telspar pipe up 0.3' in good condition and measured its position using GPS.

8-14-2018 County Survey Crew found monument removed. Set Cast Iron Cap on 5' telspar pipe at surface at previously GPS position.