Certificate of Location of Government Corner

ID#: 621106 **Description:** 1/4 SEC COR 10 11 62 **Date Set:** 11/26/1997 **County:** Olmsted

Section: 11 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 4' west of N-S fence and 2 1/2' north of fence east
MnDOT Spike & Disc in east face of PP, up 3' - N 1°34' E 134.74'
MnDOT Spike & Disc in west face of wood fence post, up 1' - S 12°25' E 13.50'
MnDOT Spike & Disc in east face of PP, up 2' – S 0°21' E 240.85'
Post with sign 1 1/2' east
This corner is located by GPS measurement

Corner History:

10-1872 T. Hunter Bk. A. Pg. 209 found the 1/4 post in the mound and set the sixteenth stone to the West. Hunter P. 209 No. 217 S 10 W. Hurlbert, N. Coe found 1/4 post in fence standing in mounds. 1/16 West set stone M & L 20.05 S 89° 55' E. Measure North 40.06' to NE 10 a corner set.

6-1893 W. Fraser Bk. A. Pg. 511 found the stake and set a stone 6" by 10" by 18" in it's place and found the sixteenth stake West and set a stone 7" by 7" by 15" in it's place. Found stake P. 209 by fence . Set 6 by 10 by 18 stone in place of stake. 1/16 West found stake in stones - replaced with 7 x 7 x 15. See Center 10 for 1966 RP's to 1/16 corner.

9-1966 J. Kerr B 94 P 53. Dug extensively by corner 3 way fence E-N-S. Found several stones (none 6 x 10 x 18). Set iron just west of 3 way fence corner post. This area is too wet and black soil for CIM must have long pipe. Depth of soil unknown. Found 1/16 stone as recorded west - stone 7 x 7 x 15 which came in small wooded island. Center large oak tree in island SW 7.6'. 3" metal U S 14 RW marker standard. W.S.W. 1.25' Center pavement south likely on 1/16 line 149.1' Measure from 1/16 stone south to 1/16 stone 2645.1'

5-11-1972 County Surveyor set 1 1/2"x3 1/2' long pipe by line from the West over the sixteenth stone and doubling the distance from the sixteenth stone to where the line intersected the N.-S. Section line at 1323.08'

11-21-1997 County Surveyor found 1 1/2" pipe up 0.5' with channel post along side of it. Pipe is 4' W + 2.5' N of corner post fences N-S-E.

11-26-1997 County Surveyor set 6' CIC p² in place of 1 1/2" pipe as Cor. With Sign and Post 1.5' East of Cor.

11-25-2003 Mn/DOT survey crew found monument in good condition.

8-25-2004 County Surveyor found cast iron cap on telspar pipe up 0.3' in good condition.

4-5-2007 County Surveyor found telspar pipe w/CIC up 0.5' in good condition but loose. The pipe would travel 2-3 tenths up or down. Pushed pipe as far down as it would go, about 0.3'.

10-28-2013 MnDOT Survey Crew found 2" Square Pipe with Cast Iron Cap.

05-19-2014 MnDOT Survey Crew set 3 new ties: Spike & Disc in east face of PP, up 3' - N 1°34' E 134.74'; Spike & Disc in west face of wood fence post, up 1' – S 12°25' E 13.50'; Spike & Disc in east face of PP, up 2' – S 0°21' E 240.85'