Certificate of Location of Government Corner

ID#: 621205 **Description:** SEC COR 11 12 13 14 62 **Date Set:** 8/20/2004 **County:** Olmsted

Section: 12 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 8' south of centerline of E-W twp road, 26 1/2' west of centerline field drive north, 9' east of fence south and in line with fence north
Punch hole in W end 15" CMP NNE 40.37'
Punch hole in E end 15" CMP NE 52.99'
This corner is located by GPS measurement

Corner History:

9-1853 Set by William Jones 51.50: Brook 10 lks wide runs East and enter dry bottom 65.00 Leave bottom 80.00 Set post at corner to sect. 11, 12, 13, & 14. Deposited charred stake. Made mound trench and pits planted Burr Oak acorns, E., E, and SW plum seeds SE & NW.

June 1867 H.E. Horton, Pg. 86 No. 132 Shows Sec. Cor. (See survey or interior of Sec. 11).

6-1875 T. Hunter P. 281 No. 278 found remains old stake in center road, in line old fence. Set stone in its place 3 x 8 x 14. 1/16th North set stake with stones on N & S sides M & L 20.02 1/2.

9-1891 Thos Fraser P. 454 No. 438. Corner gone in road building, reset corner with boulder 8 x 8 x 16 by projecting line from stake at 1/4 cor north over 1/16 cor. As placed by Hunter p. 281. Meas. 19.99 3/4 each. Meas West 39.90 1/2 to stone set M & L N 89° 40' N

5-17-1965 J. Kerr found boulder stone as recorded and set permanent marker of a Cast Iron Monument over rod.

8-1-1973 County Surveyor set CIM over deep CIM.

1-15-1975 County Surveyor found CIM tilted South.

7-11-1975 County Surveyor dug beside CIM and set it up straight.

7-17-75 1/16 N. County Surveyor found fence in 1/16th area now gone. Measured north recorded 1321 + from 11-12-13-14 and dug on line to fence post E of huge Willow at 1/4 Cor 11-12. Dug 2' x 4' and probed but found nothing.

11-21-1997 County Surveyor found CIM with head broken off 6" deep in crushed rock Twp. road.

1-9-1998 County Surveyor found CIM with head broken off. Refreshed references.

6-17-2002 County Surveyor found CIM w/head broken off down 0.6' in good condition.

11-25-2003 Mn/DOT survey crew found monument with head broken off in otherwise good condition.

8-20-2004 County Surveyor found CIM without head down 0.6' in good condition. Removed broken CIM and found CIM down 2.3' in good condition. Removed CIM and found 5/8" rerod down 4' in good condition. Removed 5/8" rerod and probed boulder down 5.7'. Set 5' telspar pipe w/cast iron cap down 0.5'.

3-20-2007 County Surveyor found telspar pipe w/CIC down 0.5' in good condition.