Certificate of Location of Government Corner

ID#: 621305 **Description:** SEC COR 13 14 23 24 62 **Date Set:** 6/27/2001 **County:** Olmsted

Section: 13 **Township:** 105N **Range:** 12W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CR 142, 3' west of centerline of twp road south and 6' west of centerline of field drive north
Punch + in N end 24" CMP NE 39.7'
This corner is located by GPS measurement

Corner History:

9-1853 Set by William Jones 75.25 Brook 4 lks wide runs East 80.00 Set post at corner to Sect. 13, 14, 23, and 24 Deposited charred stake made mound trench and pits and planted Br. Oak acorns NE & SE Cherry Seeds SE & NW

6-1857 Road survey - E.P. Bicker - Surveyor - J. B. Fellows - Dept. R.J. Perry's road record book P. 65 - Co. Rd. #1. Survey says to Sec. Post = 39.67' East - 39.80' West.

8-1887 T. Hunter P. 421 No. 410 corner gone, formerly wet marshy land, T crossroads. James Price and John James formerly divided NE 1/4 23 by carefully measuring line when orig. stakes stood so doubled meas. From N 1/4 23 and 1/16 fence south and 2 rods north of line cottonwoods on S side road. Planted stone. At this point, ??? Limestone found Co. H. D. 1/16th West set stake M & L 19.98 1/2 Mr. Price and Mr. James claim they will set stone later, none at hand.

1961 county highway department B 248 found limestone. Set CIM after road grading. Meas. West 2640.83 R 2638.0 1962 Disc in P.P. SE 60.23' F.P. Disc in. NNW 52.59' S.D. tele pole NE 62.14'

6-14-1971 County Surveyor took additional reference + in N end road culv 24" NE 39.7'

6-11-2001 County Surveyor found CIM down 15" in blacktop CR #142 in good condition.

6-27-2001 County Surveyor set 1" square pipe w/cap at CIM location at surface of CR #142.

6-17-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

3-20-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.