Certificate of Location of Government Corner

ID#: 621405 **Description:** SEC COR 14 15 22 23 62 **Date Set:** 7/21/2000 **County:** Olmsted

Section: 14 **Township:** 106N **Range:** 12W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls 2.4' east of centerline of CSAH 7, 6' north of centerline of twp road west and in centerline of twp road east
Bottle cap in stub TP NNE 60'
Lug on end CMP ESE 40.57'
Ref pipe W 70.35'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes North between sections 22 and 23. 80.00 chs. Set section corner post. Br. Oak 6 in. S78°W 381 lks. Red Oak 6 in. S16°E 270 lks. Red Oak 5 in. S82 1/2°E 252 lks. Made trench.

November 1856 Thos. Hunter Pg. 18 No. 29 Show Sec. Cor. 1/16 West 19.85 1/2 M & L - B.T.'s (S 53°E 130 lks) and (S 72°W 56 1/2 lks).

7-1871 Thomas Hunter (P. 186 No. 197), County Surveyor, found remains of stake in the center of the road. 1/16 east, set stake M & L 19.94 to stake for line W & S N 1°W.
1/16 South set stake M & L 19.94 for line east S 1/2° E.

8-1887 Hunter (P. 421 No. 410) found stake P. 186 with stone by side in center of road.
(from cards: Meas south 39.92

4-1890 Thomas Fraser (P. 440 No. 421) found 3 small stones with small stake on north side and large stake on N.W. side. Accepted as corner on testimony of a Mr. Price and Mr. Fuller who were present P. 421. Set stone 2" x 8" x 16".

10-1917 John Kerr found stone. Found Center 14 and 1/4 corner 2625.75 to west. Ran south to stone section corner. 14-15-22-23 Ran east to 1/4 14-23 - 2635.7 Iron stake on line 1317.85

7-5-1968 John Kerr, County Surveyor, found limestone with small limestones and 2 stakes. J. Kerr to restore corner. Run line from S 1/4 14 West - found 1/16 iron at 1316.6 Found limestone with small limestones and 2 stakes at 1317.4 1/16 rod is .43' North of direct line .4' east of midway 1/16 cor R.P. 37.0' to center 36" burr oak SSE 11.0' south to corner post - 26' north to corner post Placed 1/2" x 17" rod over stone glass bricks, then CIM.)

5-8-1970 County Surveyor corner now comes under concrete of Co. Rd. 7. Cut cross in pavement as corner from 1968 reference points. County Surveyor (R&P) found all lugs on culverts set as ties 7-1968 - P.P. 38916 now has disc on SE side 63.65 lug on end culvert ESE 40.57 not 40.47 all other ties gone - drove pepsi cap in wood tele stub NE 60.0 61.83 NE to grading hub - cut cross in pavement cross ties - 2.52' east of centerline - .4' south of expansion joint 9.53 west of east edge new concrete pavement.

5-16-1997 County Surveyor found cross cut in concrete CR #7) 2 1/2' Centerline

5-23-1997 County Surveyor set Ref. Pipe 1" sq pipe/cap on North edge 30th St. SE 13 1/2' N centerline 30th Street SE, 67 1/2' W Centerline CR #7

6-23-1999 County Surveyor tied out corner.

7-21-2000 County Surveyor set 5/8" copper plug w/punch mark at surface from 1999 tie out.

6-17-2002 County Surveyor found 5/8" copper plug at surface in good condition.

3-20-2007 County Surveyor found 5/8" copper plug with punchmark in good condition.