Certificate of Location of Government Corner

ID#: 621406 **Description:** 1/4 SEC COR 14 15 62 **Date Set:** 7/21/2000 **County:** Olmsted

Section: 14 **Township:** 106N **Range:** 12W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls in centerline of CSAH 7 and in centerline of W 5th St east
Ref pipe SW 130.85'
Bottle cap in TP SE 153.5'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes. North between Sections 14 and 15. 40.00 chs. Set quarter section post. Deposited charred stake; made mound, trench and pits. Planted cherry seed S.W. and N.E.

7-1871 Thomas Hunter (P.186 No. 197), County Surveyor, states corner gone. Set corner at intersection of north-south section line and east-west 1/4 line of section 14. Set 1/16 corner east.

8-1891 Thomas Fraser (P. 453 No. 437), County Surveyor, found stake after duplicating Hunter's work. Set 2 stones as corner. Set 2 stones 10 x 16 x 21 and 4 x 10 x 10.
Set stake with small stone each side south on section line 10.50 chains for line west.
1/16 west set stone M & L 20.05

7-1963 John Kerr (Eyota village survey) states corner gone. Culvert at corner location. Projected line from Center 14 over 1/16 corner and set C.I.M. over 1/2" rod

6-14-1968 J. Kerr took new reference ties. Bottle cap in new telephone pole SE 153.5 Disc in new guy pole SW 128.0 Lines center road east and south exactly. New Co. Road North. Grading ties Co. HD B 301 Hub NW 70.23, Hub W 60.89, Hub SW 69.93 - bottle cap north side strut light pole ESE 97.5 Cut cross in pavement - corner near centerline pavement - near centerline road east - corner dips needle

1970 County Surveyor corner comes under concrete pavement of Co. Rd. 7. Cut cross in pavement as corner from County Highway Department reference points.

5-16-1997 County Surveyor found cross cut in concrete 0.1' E Centerline CR #7

5-28-1997 County Surveyor set 1" sq pipe/cap as ref. In field dr. W. 7' N Centerline field dr. 49' West centerline CR #7

6-23-1999 County Surveyor tied out corner.

7-21-2000 County Surveyor set 5/8" copper plug w/punch mark at surface from 1999 tie out.

6-17-2002 County Surveyor found 5/8" copper plug at surface in good condition.

3-16-2005 Yaggy Colby Associates used copper plug in survey of NW 1/4 section 15.

9-22-2006 Yaggy Colby Associates used copper plug in large survey of section 10 and 15.

3-20-2007 County Surveyor found 5/8" copper plug with punchmark at surface in good condition.