Certificate of Location of Government Corner

ID#: 621605 **Description:** SEC COR 16 17 20 21 62 **Date Set:** 4/3/2009 **County:** Olmsted

Section: 16 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of CR 102 and in centerline of E-W twp road
Bottle cap in NW side PP #40744 SW 45.15'
SW corner of concrete culvert abutement NNW 103.15'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes North between sections 20 and 21 80.00 chs. Set post at section corner. Burr Oak 8 in. N77°E 5 lks. Burr Oak 8 in. N62 1/2° W 14 lks Burr Oak 9 in. S32° W 38 lks. Burr Oak 6 in. S12° E 44 lks.

5-1882 Thomas Hunter (P.377 No. 368), County Surveyor, found stone in center of road with stake by side of stone. 1/16 west set temp stake M & L 19.91 1/2 to N 1/4 So a stake fouond a replaced with stone 2 x 10 x 22.

7-1892 Thomas Fraser (P.493 No. 467), County Surveyor, found boulder stone.

8-1898 William Fraser (P. 640 No. 576), County Surveyor, found corner described P. 493.
1/16 north found stake and stone set by Hunter M & L 19.92 1/16 east set stone 2 x 8 x 20 M & L 19.90 1/16 center SW 1/4 16. Set stone M & L 19.93 N-S 1/16 line

8-8-1973 County Surveyor dug and found limestone with pointed boulder on North side. Used limestone and drove a 1/2" rod between stones with a CIM over the limestone.

8-28-2008 County Surveyor found CIM down 1.6' in good condition.

4-3-2009 County Surveyor found CIM down 1.6' in good condition. Removed CIM and found 1/2" rerod down 3.3' in good condition. Set 3' telspar pipe w/Cast Iron Cap down 0.5' at CIM position.