Certificate of Location of Government Corner

ID#: 621606 **Description:** 1/4 SEC COR 16 17 62 **Date Set:** 5/2/1995 **County:** Olmsted

Section: 16 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 5 1/2' west of centerline of CR 102 and 55' south of centerline of field entrance east
County Survey Disk in gate post SSW 100.82'
County Survey Disk in S side PP E 33.89'
This corner is located by GPS measurement

Corner History:

9-1853 Set by William Jones 2.45 Brook 3 lks wide runs NW 8.96 Dbl. Bur Oak 8 in diam 27.40 Brook 10 lks wide runs West 40.00 Set post at gr. Sec. corner Br. Oak 9 N 1 E 1050
Br. Oak 12 S 24 E 160

8-1898 W. Fraser P 640 No. 576 corner gone. Mr. Bear avers Hunter reset stake with stone at corner which came in log culvert also set 1/16 corner south so reproduced corner from SW 16 over 1/16 corner North 19.92 M & L (1314.72d) Set stake and stone 2 x 8 x 28 center road and center log culvert. Meas. North 39.94 N20'W 2636.04 1/16 south found stake and stone set by Hunter 19.92 M & L 1314.72 1/16 east set stone 2 x 6 x 18 M & L 20.06 1/4 N 89° 40' W to center 16 a stone 2 x 6 x 22 set this survey. 1/16 Center SW 1/4 16 - Set stone M & L 19.93 on N-S 1/16 line

8-1968 J. Kerr measured north from SW corner 16

5-8-1970 County Surveyor measured east to center 16.

5-12-1970 County Surveyor set 3/4" rod as 1/16 south of above 1/14 corn by line and meas of 1318.2 over 1/16 stones east rec. 16-17-20-21 With 1/4 corner as set, 1/16 south as set and SW 16 as set meas 1313.4± M & L (R1314.7)

8-29-1973 County Surveyor found rod set 5-1970

5-2-1995 County Surveyor removed 1/2" iron set by Roger Brand in 1973 from Center 16 over 1/16 corner West of 1/4 corner. Set CIM over 1/2 Iron on E-W 1/4 line from East and on line from Sec. corner South over 1/16th corner between. The corner is 5 1/2 West of centerline CR 102. The corner is in line of main fence line west and 10 North of Elec fence line East. CSD in top of 10" x 12" CP ENE 43.55 CSD in gate post SSW 100.82

8-28-2008 County Surveyor found CIM down 0.5' in good condition.

4-13-2009 County Surveyor found CIM down 0.5' in good condition.