Certificate of Location of Government Corner

ID#: 621705 **Description:** SEC COR 17 18 19 20 62 **Date Set:** 8/31/1973 **County:** Olmsted

Section: 17 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2 1/2' west of centerline of twp road north and 15' NNW of centerline of twp road on curve
Punch hole in E end CMP NE 38.45'
County highway disk in NW side PP #15764 NE 49.23'
County Survey Disk in NW side PP #15764 NE 49.14'
Punch hole in W end CMP NW 38.07'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes North between sections 19 and 20 80.00 chs. Set section corner post. Burr Oak 12 in. N36°E 150 lks. Burr Oak 10 in. N43°W 128 lks. Burr Oak 4 in. S29°W 88 lks. Burr Oak 4 in. S41°E 89 lks

5-1882 Thomas Hunter (P. 377 No. 368), County Surveyor, found hole in soil lined with bark. Tested with stumps of SW and SE bearing trees. Set 4" x 8" x 22" limestone.

6-1883 T. Hunter (P. 348 No. 375) found stone in center of the road. P. 377.

6-1893 William Fraser (P. 512 No. 480), Colunty Surveyor, found stone placed by John Hunter P. 377 and SW bearing tree. Left as found.

10-13-1930 J. Kerr Book 4 Page 10, found stone.

4-26-1971 County Surveyor Set 5/8" x 2' rod as section corner by exact line from 1/14 17-18 over 1/16 stone making rink at 1/4 corner stone .75' west of direct line.

8-31-1973 County Surveyor dug and found that a concrete box culvert had completely destroyed corner. Set CIM over iron rod set by line and measurement from 3 stones found north.

5-30-1997 County Surveyor found CIM in good condition.

4-3-2009 County Surveyor found CIM down 0.4' in good condition.