Certificate of Location of Government Corner

ID#: 621804 **Description:** 1/4 SEC COR 18 19 62 **Date Set:** 9/18/1995 **County:** Olmsted

Section: 18 **Township:** 106N **Range:** 12W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' north of centerline of CSAH 23 and 15' west of centerline of residential driveway north
Ref pipe S 51.37'
This corner is located by GPS measurement.

Corner History:

9-1853 Set by William Jones 38.70 set post at gr. Sec. corner Br. Oak 4 N 81 W 232
Br. Oak 5 S 40 E 114

6-1883 T. Hunter P. 384 No. 375 corner gone. Bearing trees gone, no evidence of knowledge. Set stake on sec lin which 10 the overrun bly measure. Total mile 78.80 Gov't measure 78.70 Meas east 40.05 2643.3 Meas west 38.75 2551.5

6-1893 W. Fraser P. 512 NO. 480 could not find stake or any evidence to relocate it. Set stone after measure south line 18 short 6 1/2 links. Meas east to stone found 39.96 3/4 (2637.85) Meas west to 1/16 west stone at 19.98 3/8 (1318.92) on line and prop meas Meas above 1/16 west to sec cor 18.68 3/8 (1233.13) drove iron stake M & L 9.34 3/16 (616.57) chs for line north 1/16 north drove stake M & L 19.90

10-1930 J. Kerr Book 4 P. 10 Found stone Measure east 2639.2' to stone Measure west 2552.16'

6-12-1978 (1/16 West) County Surveyor dug with the backhoe and found a 3" x 5" x 8" red boulder over a stake 3' deep. Set a 1/2" x 26" iron in the stake hole.

8-20-1981 1/16 North: County Surveyor dug from a point 1/2' North of the traverse nail for 3 1/2' North, 3' East, and 2' West by 2' deep to clay on rock. Found only one mark that was a possible stake mark 2.4' N and .3' West of the t.n. but very questionable.

6-20-1995 County Surveyor found P.K. Set @ comp. Location. Set 1" square pipe with cap on back slope 51' south of centerline CR #23.

9-18-1995 county highway department set 1" square pipe with cap.

10-10-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.