# Certificate of Location of Government Corner

**ID#:** 621904 **Description:** 1/4 SEC COR 19 30 62 **Date Set:** 4/1/2009 **County:** Olmsted

**Section:** 19 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

The corner falls in centerline of CR 123 and in line with fence south
County Survey Disk in E side PP S 61.57'
County Survey Disk in SE side PP NE 84.88'
Ref Pipe S 64.95'
This corner is located by GPS measurement

**Corner History:**

9-1853 Set by William Jones 14.10 Brook 3 lks wide runs NW 29.69 Burr Oak 6 in. diameter 38.75 set post at gr. Sec. corner - true line 62.40 Brook 8 lks wide runs North 68.80 Bend of same runs SW 71.00 same brook runs North

6-1883 Hunter P 384 No 375 Sec 19 John Huges Found stake set P 332 Measure East to sec. corner Stone 39.93 Measure west to sec corner stone 38.74 Bearing noth to stone at Center 19

6-1913 D. Williams Page 222-3 B Did not use 1/4 19-30 - could. See entire mile run this traverse Very carefully set woodstakes. A Mr. Neal Avers he would set steel stakes at corners.

6-1968 J. Kerr for Eyota Town Board. Measlure from SE 19 to fence running south. Rough measure as farmer held measure. Came 2632 - record 2634+. Dug extensively. Found place where old post of large size originally stood, nails, staples etc. Set rod in hole to hold spot. Looked for 1/16 stone west extensively with shovel and bulldozer. After brushing at SW 19 could see entire mile from about station 2000 from east. Found iron set to be slightly south 1.0'± so set rod on direct line in line fence south about 2632 from SE corner. Set 1/2" rod at 76.35' south then 176.35 set 1/2" rod. 1/16 West on securing line readily found 1/16 stone 3 x 4 x 15 set by Hunter in 1878. It will be destroyed by road grading. RPs as follows: Set 16d nail (bent in driving in root of 14" white oak on east side 125.27' from stone. Then on transit line set rod at 200' which came .8' North of tree with deep rough bark. Both trees lightly blazed toward corner.

7-24-1968 J. Kerr found steel rod in place of original stake. Set permanent marker of Cast Iron Monument.

7-29-1993 county highway department tied out corner for road construction.

3-24-1994 county highway department set 3/4" iron.

8-23-1995 County Surveyor found 3/4" iron set by county highway department in 3-1994 from reference pipe with cap.

6-4-2004 County Surveyor found 3/4" iron down 0.2' in good condition.

6-26-2008 County Surveyor found 3/4" rerod down 0.3' in got赔□