Certificate of Location of Government Corner

ID#: 621906 **Description:** W 1/4 SEC COR 19 62 **Date Set:** 4/14/2009 **County:** Olmsted

Section: 19 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls on north side slope of ravine, 19 1/2' north of centerline of creek and 18' south of E-W fence
20d spike in S side blazed 24" Burr Oak E 27.75'
20d spike in SW side blazed 18" Burr Oak NW 38.14'
Sign on 9" Elm 3' NW
This corner is located by GPS reference stations "Dozen A & B"

Corner History:

1853 Gov't Notes Ball, Deputy Surveyor. North between 19 and 24. 35.53 Br. Oak 12 in. 40.00 set quarter post. Br. Oak 10 in. S85E 13 lks. Br. Oak 14 in. N15W 64 lks. 40.72 Br. Oak 12 in.

6-1883 T. Hunter P.384 No.375 corner gone but both B trees standing. Reset corner. Stone 2x6/15x24" from witness trees. Set approx corner west at 9.98 at good chainage but est. line from E-W 1/4 line S18 S.24 bad shape.

4-1884 T. Hunter P.387 No.378 found stone P.384. Established line west but destroyed it after survey so some parties wouldn't profit from work that didn't pay.

6-1901 Robert Fraser P.706 No.620 found stone P.384 tested B tree. Corner lies under fence a little north of fence running east. 1/16 west drove stake M&L to center 24 which this time was set a stake and stone and B trees. 10" Burr Oak S17E 44 lks, 3" Burr Oak N66-3/4E 31-1/2 lks. Gov't B trees W 1/4 19. 10" Burr Oak N87°W 39, 12" Burr Oak S81°E 62 (not BT's given in gov't notes).

8-20-1969 County Surveyor found limestone as recorded. Set permanent marker of a Jack Bar by side of stone.

1-20-1989 Roger Brand visited corner, did not find steel jack bar. Found 2"x10" limestone top, top sticks up ± 6" but is leaning to the south.

4-14-2009 County Surveyor found 2" x 6"/15" x 22" stone w/Jack Bar leaning south. Removed stone and Jack Bar and set 2' telspar pipe w/Cast Iron Cap up 0.5' from ties in trees.