Certificate of Location of Government Corner

ID#: 622004 **Description:** 1/4 SEC COR 20 29 62 **Date Set:** 9/18/1995 **County:** Olmsted

Section: 20 **Township:** 106N **Range:** 12W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 6' south of centerline of CSAH 23 and 191' east of centerline of residential driveway north
Ref pipe S 50.07'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes William A. Jones, Deputy Surveyor, Set post at quarter corner to sections 20 and 29. 39.95 chs. - Erected mound with trench and pits.

5-1882 Thomas Hunter, County Surveyor, (P 377 No. 368) found Stone in center of road, tested OK by NW bearing tree.

7-1892 Thomas Fraser, County Surveyor, (P493 No. 467) found recorded Stone.

7-20/24-1978 County Surveyor dug with backhoe in CSAH 23. Found 4" x 12" x 15" stone boulder flush with surface of old road and 6' South of C/L. Set Iron along side of stone. Set 1/2" x 20" Iron at road surface over stone.

6-19-1995 County Surveyor found Iron 6' South of C/L CSAH 23. Made reference ties to quarter corner before resurfacing road.

9-18-1995 County Surveyor had County Highway Department set flush, from reference ties, 1" square pipe and Aluminum Cap with RLS #15809.

3-10-1997 Gerald Stephas, Mn/DOT Survey Crew Chief, recovered the 1995 1" square pipe and Aluminum Cap with RLS #15809, updated the topography and measured new reference ties.

For details and survey analysis, contact the Minnesota Department of Transportation Surveys Office in Rochester, Minnesota.

4-2-2009 County Surveyor found 1" square pipe w/cap at surface in good condition.