Certificate of Location of Government Corner

ID#: 622104 **Description:** 1/4 SEC COR 21 28 62 **Date Set:** 9/18/1995 **County:** Olmsted

Section: 21 **Township:** 106N **Range:** 12W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' north of centerline of CSAH 23, in line with fence north and 12' east of centerline of field drive south
County Survey Disk in SE side PP #15675 NE 48.60'
Ref pipe N 52.30'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes William Jones. 39.94-1/2 set post at quarter sec corner. Bur Oak 9 S74W 25. Burr Oak 10 N6W 103.

4-1863 P.C. Compton P.69 No.97 shows 1/4 stake used to set center 28 at intersecting lines.

7-1892 W. Fraser P.493 No.467 S.21, N. Dugan. Corner gone, set stone 1lkx1-1/2lkx2-1/2lk (7"x11"x20") M&L 39.87. 1/16 north set limestone M&L 20.00 to center boulder stone. 1/16 west set stake M&L 19.93-1/2.

5-1896 T. Hunter P.600 No.545 S.28, W. Bussian, corner gone, set stone 16x16x24 boulder M&L 39.85-1/2. 1/16 west set boulder stone M&L 19.92-3/4 (Hunter usually finds stone if any,same deal NE 28. No B trees or other evidence, chainage similar cant figure it).

6-15-1978 County Surveyor dug and found Hunter's 16x16x15 boulder 3-1/2' deep. Dug 7' by 4'. Set a 1/2"x2' rod on the north side of the stone and a 5/8"x21" iron on the south side.

6-16-1978 County Surveyor set a 1/2x25" rod 0.3' N and 2.1' E of the t.n. and over the stone found. RP's: CSD SE side PP #15675 NE 48.60. Punch "+" in top center (in 6") W end 15" CMP SW 42.78 corner 1' N of centerline and in line with fence N.

6-19-1995 County Surveyor found 1/2" iron. Set 1" square pipe w/cap 51' south of centerline CR 23 and 5' east of property split south. Angle at Ref. pipe, Angle RT center top of white topped silo ENE to 1/4 corner 21-28 269° 41' 00" to 1/4 corner 21-28 (1/2" iron) VA 88° 12' 15" dv 06 slope 52.33 Hor 52.30.

9-18-1995 county highway department crew set 1" square pipe w/cap at surface from 6-19-1995 reference location.

8-20-2001 County Surveyor found 1" square pipe w/cap at surface in good condition.

4-2-2009 County Surveyor found 1" square pipe w/cap at surface in good condition.