Certificate of Location of Government Corner

ID#: 622105 **Description:** SEC COR 20 21 28 29 62 **Date Set:** 9/18/1995 **County:** Olmsted

Section: 21 **Township:** 106N **Range:** 12W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1/2' north of centerline of CSAH 23 and in centerline of CR 102 north
State Reference Point in NE side PP #15652 NW 46.68'
Ref pipe NNE 83.68'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor. Set post at corner to sections 20, 21, 28, and 29. 80 chs. Erected mound with trench and pits.

7-1892 Thomas Fraser (P493 No. 467) could not find the corner. Measured SE 21 to S1/4 20 (119.65 chains). Projected line SW 20 over S1/4 20 and NW 21 over W1/4 21 to test location. Set Limestone as corner.

5-1896 T. Hunter (P 600 No. 545); corner and bearingn trees gone. Measures SE 21 to SW 20 (159.44 chains). Measured from NW 21 to a temp. point set midway on aforementioned East-West line. Found original stake down 1.5' badly rotted within a foot of 79.63 chains measured from NW 21. Set stone in place of old rotted stake.

1945 County Highway Department measured reference ties.

11-1961 Lauren DuVal, M.H.D., found inplace Hard Head with nob on East side, old hub over it. Set 3/4" I.P.

6-15-1978 County Surveyor dug down and found a 3/4" rod over a large flat boulder, over a 3" x 8" x 13" pointed boulder (with a stake on East side) packed in small limestone and sitting over old stake as described by Hunter 4' deep. Set the 3/4" Iron in old stake hole and reset the boulder over it. Set large flat boulder on East side. Set 1/2" rod at road surface over corner. Corner in C/L East-West road and 1' West of C/L of road North.

6-16-1978 County Surveyor set 1/2" rod at road surface over old stake found RP's: MHD Disc in NE side PP #15652 NW 46.67' CS Disc in NW side (up 5') cut off telephone pole utility box NE 50.77'

6-19-1995 County Surveyor found 1/2" Iron. Made reference ties to corner before resurfacing road.

9-18-1995 County Surveyor had County Highway Department set flush, from references ties, 1" square pipe and Aluminum Cap with RLS #15809.

4-22-1997 Gerald Stephas, Mn/DOT Survey Crew chief, recovered the 1995 1" square pipe and Aluminum Cap with RLS #15809, updated the topography and measured new reference ties.

For details and survey analysis, contact the Minnesota Department of Transportation Surveys Office in Rochester, Minnesota.

4-2-2009 County Surveyor found 1" square pipe w/cap at surface in good condition.