Certificate of Location of Government Corner

ID#: 622106 **Description:** 1/4 SEC COR 20 21 62 **Date Set:** 4/13/2009 **County:** Olmsted

Section: 21 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of CR 102 and 1' north of fence row west
Punch hole in E end 15" CMP NE 23.48'
Punch hole in W end 15" CMP WNW 20.05'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes North between sections 20 and 21 40.00 chs. Set quarter section post. Burr Oak 6 in. N831/2°W 34 lks. Burr Oak 10 in. N81 1/2°E 108 lks.

5-1882 Thomas Hunter (P. a377 No. 368), County Surveyor, states corner gone. Relocated corner from NW bearing tree stump and set a temporary stake. A Mr. Bear will set stone at that point. Corner falls in line with fences east and west.

7-1892 Thomas Fraser (P. 493 No. 467), County Surveyor, found boulder stone set by Mr. Bear in place of original 1/4 corner set by Hunter.

8-29-1973 County Surveyor dug and found stone 5.8' deep. Set a CIM over a 1 1/4" x 3' pipe over stone. Corner falls 1' west of center of north-south road and 1' south of fence west.

4-9-2009 County Surveyor found CIM with head broken off down 1.1' in good condition.

4-13-2009 County Surveyor removed CIM and found 1 1/4" pipe down 2.9' in good condition. Removed pipe and set 5' telspar pipe w/Cast Iron Cap down 0.4' at CIM position.