Certificate of Location of Government Corner

ID#: 622109 **Description:** SEC CEN 21 62 **Date Set:** 8/9/2010 **County:** Olmsted

Section: 21 **Township:** 106N **Range:** 12W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' west of N-S fence and in line with fence east
The monument is down 0.1'
20d spike in hub in W side Burr Oak NNE 23'
Post with sign east 2'
This corner is located by GPS measurement

Corner History:

7-12-1892 Thomas Fraser, County Surveyor, (Book A, Page 493, No. 467) set boulder stone at intersecting quarter lines. 1/16th South set limestone midway and on line at 20.00 chains (1320.00') to South 1/4. 1/16th East set limestone midway and on line at 19.93-1/2 chains (1315.71') to East 1/4.

8-11-1969 John Kerr, County Surveyor, found large boulder as recorded. Set Cast Iron Monument over 3/4" x 10" rod with pieces of boulder packed around monument.

2-3-2003 GGG used monument for section breakdown for survey in the SW 1/4 Section 21.

8-9-2010 County Survey Crew found Cast Iron Monument in good condition with head broken off. Removed Cast Iron Monument and found 3/4" rod below. Set 5' telspar pipe with cast iron cap down 0.1' over 3/4" rod and measured its position using GPS.

4-30-2018 Mark Severtson, County Surveyor, recommends using the computed intersection of quarter lines for the center of section. Based on the county's section breakdown, the Cast Iron Cap on telspar pipe, as located by GPS in 2010, falls 1.90' south and 0.62' east of the computed center.