# Certificate of Location of Government Corner

**ID#:** 622205 **Description:** SEC COR 21 22 27 28 62 **Date Set:** 9/18/1995 **County:** Olmsted

**Section:** 22 **Township:** 106N **Range:** 12W **Monument Description:** 1" square pipe w/cap RLS #15809

**Reference Ties:**

The corner falls 2' north of centerline of CSAH 23 and 2 1/2' east of centerline of N-S twp road
Ref pipe SW 75.20'
This corner is located by GPS measurement

**Corner History:**

1853 Gov't Notes North between sections 27 and 28. 80.00 chs. Set section corner post. Burr Oak 4 in. N21ºE 126 lks. Burr Oak 8 in. S73ºE 313 lks. Burr Oak 4 in. S59 1/2W 181 lks. Burr Oak 8 in. N1 1/2ºW 145 lks.

7-1892 William Fraser (P. 493 No. 467), County Surveyor, states corner gone. Used unmarked tree avered as bearing tree to located corner. Also ran and measured line from SE corner 22 which proved bearing tree. Placed boulder stone as corner. Bearing tree: S 59 1/2ºW 181 lks.

5-1896 Thomas Hunter (P. 599 No. 545) fround large boulder with drill hole.

5-1902 William Fraser (P. 14B), County Surveyor, found stone and bearing tree of P. 599.

7-1939 John Kerr (P. 488B) County Surveyor, found large boulder and bearing tree S54ºW 120.5'.

11-1961 M.H.D. (DuVal) found boulder in center of road-iron riser.

6-8-1973 County Surveyor dug hole in black top with backhoe and found boulder with drill hole 3.1' north and .3' East of iron rod used by county and state and private surveyors. Set rod over stone. B.T. still standing.

6-10-1974 County Surveyor set a CIM over short pipe over stone.

6-19-1995 County Surveyor found CIM. Set 1" square pipe w/cap in SW cor cross roads Int. 58' south of centeline CR 23 and 43-1/2' west of dead end road south. Angle at Ref. pipe, angle RT P.K. in PP #15685 (2nd pole N on W side twp rd N) to sec corner 36° 10' 46.5". to sec corner 21-22-27-28 (CIM) VA 89° 21' 36" dv 13. Slope 75.20 Hor 75.195.

9-18-1995 county highway department set 1" square pipe w/cap at surface from 1995 overlay tie out.

4-2-2009 County Surveyor found 1" square pipe w/cap at surface in good condition.