Certificate of Location of Government Corner

ID#: 622305 **Description:** SEC COR 22 23 26 27 62 **Date Set:** 7/21/2000 **County:** Olmsted

Section: 23 **Township:** 106N **Range:** 12W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls 0.4' west of centerline of TH 42, in centerline of CSAH 23 west and 4' south of centerline of twp road east
County highway disk in SE side stub TP NE 62.12'
Geodetic Marker "Bear Az" NNW 88.71'
Ref pipe E 84.16'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes Williaim A. Jones, Deputy Surveyor North between sections 26 and 27. 80.00 chs. Set post at corner to sections 22, 23, 26, 27. Red Oak 5 in. N79ºW 192 lks. Bur Oak 4 in. N41ºE 74 lks. Red Oak 5 in. S20ºW 65 lks. Red Oak 6 in. S16ºE 138 lks.

12-1857 E.P. Bircher, Surveyor, and J.B. Fellows, Deputy, (CR 85) surveyed the road on the section line between sections 23 and 26 and between sections 22 and 27.

4-1890 Thomas Fraser, County Surveyor, (Book A, Page 440, No. 426) "took the line of the 1/4 and Sec. corner North and two trees standing NE and one SE as B.T. On digging found the remains of two stakes one less rotted above and beside one that was completely rotted, but the pulverized wood could be traced to a point. These two trees before spoken of agreed as to measurement but varied a trifle as to course, set here a stone 11" x 20" x 20"." He set a stone 3" x 10" x 16" at the 1/16th West midway and one line to a stake and stones found at 1/4 corner 22-27 (set stone in its place).

5-1902 William Fraser, County Surveyor, (Book B, Page 14) found boulder stone, also SE and NE bearing trees tested by measurements given in Field Notes and found correct.

8-1934 County Highway Department (C.H.D. Book 53) shows a hub at the corner.

8-1945 County Highway Department (C.H.D. Book 136) shows a 1/2" rod at the corner. Also found the stone at the 1/16th West.

1961 M.H.D. (Cert Book) shows a 1/2" rod at the corner.

11-1967 County Highway Department (C.H.D. Book 301) shows a Cast Iron Monument in place of the 1/2" rod at the corner.

4-1971 County Surveyor visited the corner. CR 7 is now concrete surface. Found only two remaining reference points, one NE and one SW.

6-1973 County Surveyor found the stone at 1/4 corner 22-27. Set a CIM over it.

6-15&16-1978 County Surveyor found the stone at the 1/16th West of Sec. corner 22-23-26-27. Set a 1/2" rod over the stone.

9-25-1979 County Surveyor, only two reference points, one NE and the other SW, remain for this corner and we could not get a satisfactory corner location from. The County Surveyor therefore set a 1" square by 2' long pipe with cap as the corner on line and at double the measure from 1/4 corner 22-27 over the 1/16th East.

5-16-1997 County Surveyor found 1" square pipe w/cap in concrete CR 7 0.4' W centerline.

5-23-1997 County Surveyor set 1" square pipe w/cap as Ref. on N edge 40th St SE 10' N centerline 40th St SE 83' E centerline CR 7.

6-25-1999 County Surveyor tied out corner.

7-21-2000 County Surveyor set 5/8" copper plug w/punch mark from 1999 tie out.

4-2-2009 County Surveyor found 5/8" copper plug w/punch mark at surface in good condition.