Certificate of Location of Government Corner

ID#: 622309 **Description:** SEC CEN 23 62 **Date Set:** 4/28/2000 **County:** Olmsted

Section: 23 **Township:** 106N **Range:** 12W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
120d spike

Reference Ties:

The corner falls in centerline of N-S twp road, in centerline of farm entrance west and 7 1/2' north of centerline of field entrance east This corner is located by GPS measurement

Corner History:

7-14-1871 T. Hunter P.186 No.197 set stake at inters lines. 16 west set corner M&L 19.91 1314.06 S89-3/4°W. 16 north set stake M&L 19.93 1315.38' N0°50'W. 16 center NW 1/4 23 set stake inters lines. Meas south 39.81 2627.46'.

8-12-1887 T. Hunter P.421 No.410 no mention of corner, used extensively. 16 east set stone M&L 19.95 1316.7. Meas south 39.81 2627.46'. Meas north 39.86 2630.76. Meas west 39.82 2628.12'

9-7-1973 County Surveyor found perfect chisel pointed limestone.

6-23-1983 County Surveyor could not dip corner but RP's in place may be deep.

12-13-1994 Yaggy Colby was at corner. Ties to power poles are gone. Shed is torn down but conc. slab is still in place. They checked distance to S 1/4 cor and they think they are within 0.10' ± they took two new ties to drill hole N end 15" culvert ENE 32.31' to drill hole S end 15" culvert SE 40.00

4-28-2000 County Surveyor found pk at surface and checked ties. Removed pk and dipped, found nothing. Set 120d spike at surface.

5-12-2003 Land Consultants found and used monument at center of section 23.

4-1-2009 County Surveyor found 120d spike down 0.2' in good condition.