Certificate of Location of Government Corner

ID#: 622405 **Description:** SEC COR 23 24 25 26 62 **Date Set:** 7/23/2009 **County:** Olmsted

Section: 24 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The monument is down 0.5'
The corner falls 3' north of centerline of E-W twp road and 1 1/2' east of centerline of N-S twp road
County Survey Disk in SE side PP NE 43.95'
County Survey Disk in SW side PP NW 43.29'
60d spike in E side 20" Walnut SW 85.35'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes William A. Jones, Deputy Surveyor. North between sections 25 and 26. 80.00 chs. Set post at corner to sections 23, 24, 25, and 26. Deposited 3 flint 2" square. Made mound trench, and pits, and planted plum seeds NE and SW planted cherry seeds SE and NW.

6-1913 David William's (P. 224B), County Surveyor, found boulder in the center of crossroads avered by adjacent land owners as being the section corner. Set pipe as 1/4 corner 25-26.

11-1961 M.H.D. set 3/4" iron riser over boulder.

9-5-1973 County Surveyor dug with backhoe and found MHD rod set over small subsoil boulder lying flat which could not have been the corner. Dug further and found 2" x 4" board 18" long which appeared dug in. Board 2' deep and standing vertical. Location of 2" x 4", 4.5'N and 2.8'E of MHD rod, fit William's' measure south to his pipe (found) better than the MHD rod. Accepted 2" x 4" as corner and removed MHD rod.

7-11-1975 County Surveyor dug down to 2" x 4". Set rods on the East and West sides and CIM over all.

6-8-2001 County Surveyor found CIM down 1.1' in good condition.

7-23-2009 County Surveyor found CIM down 1.1' in good condition. Removed CIM and found 2" x 4" x 24" board with boulder on west side down 2.8' in good condition. Removed board and reset CIM over 1/2" x 14" rerod down 0.5' at CIM position.

9-21-2011 County survey crew found CIM in good condition