Certificate of Location of Government Corner

ID#: 622506 **Description:** 1/4 SEC COR 25 26 62 **Date Set:** 10/16/1974 **County:** Olmsted

Section: 25 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 5' south of north FAI-90 R/W fence and in line with centerline of twp road north
Minnesota Highway Disk reference monument NNE 42.3'
Post w/sign 1' south
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes North between sections 25 and 26. 40.00 chs. Set post at quarter section corner. Deposited handful of flint. Made mound, trench, and pits. Planted cherry seeds NE and SW.

5-1902 William Fraser (P. 14B), County Surveyor, found old stake in center of road in line with fence east. Set stone 2" x 6" x 22" in place of stake.

6-1913 David William's (P. 224B), County Surveyor, could not find corner. Set 1" x 4' iron pipe midway and on line.

11-1961 M.H.D. (DuVal) found nothing. Set a 3/4" rod in line with east-west fence and in center line of road.

9-5-1973 County Surveyor dug north of I-90 R/W fence with backhoe for William Fraser's Stone and found William's pipe and DuVal's iron. Ran line from 1/4 corner 26-27 over Center 26 and found Fraser's limestone 4.7' south of I-90 R/W fence down 2". Set irons on east and west sides. DuVal rod lies 6.4' north and 2.5' west (pulled rod). William's pipe lies 7.3' north and 6.0' west (left down 18").

6-10-1974 County Surveyor lowered stone and set CIM over 3/4" iron above stone.

4-20-2009 County Surveyor found CIM down 0.6' in good condition.