Certificate of Location of Government Corner

ID#: 622604 **Description:** 1/4 SEC COR 26 35 62 **Date Set:** 9/20/1995 **County:** Olmsted

Section: 26 **Township:** 106N **Range:** 12W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CR 129 and 2' west of fence south
Punch hole in top E end CMP S 31.46'
Punch hole in top W end CMP SW 38.91'
County Survey Disk in NW side PP #1764 SW 62.36'
Ref pipe S 48.20'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes W.A. Jones, Deputy Surveyor. West on true line between sections 26 and 35. 40.00 chs. Set post at quarter section corner. Bur Oak 7 in. N 17 1/2W 61 lks. Bur Oak 8 in. S 16 W 63 lks.

4-1863 P.C. Compton P.68 No.96 shows 1/4 stake used to set center sec 35 at intersecting lines.

5-1902 William Fraser (P. 14B), County Surveyor, found stone in the center of the road.

1965 county highway department (B. 165) found limestone. Set CIM.

10-3-1975 County Surveyor dug down to verify County Highway Department CIM. Found CIM over 3" x 9"/6" x 12" limestone 2.4' deep with glass beneath in clay. Set scrap iron by stone and left CIM in place.

6-19-1995 County Surveyor found CIM. Set P.K. at surface. Set 1" square pipe w/cap 47' south of centerline CR 129 and 2' west of fence line south. Angle at Ref. pipe, angle RT P.K. in PP #1763 (1st pole east on S side CR 129) to 1/4 corner 270° 03' 58.5" to 1/4 corner 26-35 VA 88° 27' 40" dv 04 slope 48.215 Hor 48.195.

9-20-1995 county highway department set 1" square pipe w/cap at surface from 1995 tie-out..

4-9-2009 County Surveyor found 1" square pipe w/cap at surface in good condition.