Certificate of Location of Government Corner

ID#: 622606 **Description:** 1/4 SEC COR 26 27 62 **Date Set:** 7/21/2000 **County:** Olmsted

Section: 26 **Township:** 106N **Range:** 12W **Monument Description:** Corner falls on I-90 bridge 50.00' S of Witness Corner
Witness Corner: 1" square pipe w/cap RLS #15809

Reference Ties:

Witness Corner: The corner falls 17 1/2' west of centerline of TH 42 and 41 1/2' north of end of bridge deck
Post w/sign 10' west
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 26 and 27. 40.00 chs. Set quarter section corner. Bur Oak 4 in. N 34ºE 84 lks. Red Oak 5 in. S51ºW 50 lks.

5-1856 Thomas Hunter, County Surveyor, (Book A, Page 6, No. 10) possibly used this corner to set the Center 29 which was used for a survvey in the W 1/2 Sec. 27.

5-1902 William Fraser, County Surveyor, (Book B, Page 14) states that the corner was lost so set a stone 20" x 6" x 4" for corner on line and midway between the section corners. He used the corner to set the 1/16th North, the 1/16th South, the 1/16th East, the Center 26, the 1/16th West, and the Center 27.

8-1934 County Highway Department. (C.H.D. Book 53) found 4" x 6" x 20" limestone with part of top broken off (stone 20.3 West and 1.5 North of P.I. Station 213+13.9 S.A.P. 2402-B). Reference stone and took stone out and laid it on fence line 33' West - to be replaced when grading complete.

1961 M.H.D. (Cert. Book) assumed corner. Set 3/4" rod.

1967 County Highway Department (C.H.D. Book 301) found M.H.D. 3/4" rod.

9-1973 County Surveyor projected the line from the E 1/4 corner 26 (found) over the Center 26 (found) and the line from the W 1/4 corner 27 (found) over the Center 27 (a temporary point set after finding the 1/16th South and the 1/16th North, both set by Will Fraser, and the N 1/4 corner 27) and the two lines agreed by a few tenths. The corner falls in the I-90 Bridge. Set nothing.

11-21-1974 County Surveyor set Sec. Corner 26-27-34-35 (See Certificate Filed).

9-25-1979 County Surveyor set Sec. Corner 22-23-26-27 (See Certificate Filed)

9-25-1979 County Surveyor set 1/4 corner 26-27 midway and on line between the section corners as in Will Fraser's survey P. 14 Book B. Rechecked the line from the E 1/4 corner 26 over the Center 26 by electronic traverse and found this line to come just 1.29' south of the corner as set. The corner falls on the I-90 Bridge so we could not set a monument. Set a railroad spike 50.00' north and on the section line as a reference point.

5-16-1997 County Surveyor found RR spike witness corner in good condition 17-1/2' W of centerline.

6-25-1999 County Surveyor set ref pipe and tied out witness corner.

7-21-2000 County Surveyor set 1" square pipe w/cap as witness corner at surface from 1999 tie out. Witness corner falls 17 1/2' west centerline CSAH 7 and 41 1/2' north end bridge deck.

4-20-2009 Witness Corner: County Surveyor found 1" square pipe w/cap at surface in good condition. Set post w/sign.