Certificate of Location of Government Corner

ID#: 622609 **Description:** SEC CEN 26 62 **Date Set:** 5/1/1902 **County:** Olmsted

Section: 26 **Township:** 106N **Range:** 12W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
8" x 20" boulder w/drill hole

Reference Ties:

The corner falls 10' south of north FAI-90 R/W fence and 89 1/2' north of centerline of WBL of FAI-90
This corner is located by GPS measurement

Corner History:

5-1902 W. Fraser P.14B set stone with hole cut in top boulder 20x20x8 at true inter lines. 1/16 north set stone 9x9x20 M&L 19.94. 1/16 south set temp stake M&L 19.89-1/2 for line west. 1/16 west set stone 2-1/2x7x12 M&L 19.89 1312.74. Meas east 40.03 to stone 2x6x22 centerline road 2642.0.

6-1913 D. Williams P.224B found boulder with hole in top P.14B. 1/16 west found limestone 3"x4" top 1313.2. Meas east rather indefinate 2626.4 which was double the distance from center to 1/16 west not a conclusive deduction as Fraser had 40.03 to stone. Fraser had 1312.74 against 1313.2 for the meas from center 26 west to 1/16 stone set M&L.

9-6-1973 County Surveyor found recorded 8x20x20 recorded boulder with hole in top close to surface. 9.25' south of I-90 N.R.W. fence in line of farm fence north. I-90 grading did not cut away any dirt at all so stone close to surface yet. Drove 5/8"x14" irons on N and S sides and 1x2 hubs on E and W sides. No other RP's left stone as found. Elect meas W 2625.75 E 2643.15 N 1316.02 2631.95 R2625.48 2642.0 1316.04 each 1/2. 1/4 26-27 will be adjusted .2' N of mark on bridge if can be found. Later RP 26.1' NW to I-90 RW marker.

1-21-2009 LaCrosse Engineering & Surveying found and used boulder stone with iron pipes on North and South sides as center of section 26.

4-29-2009 County Surveyor found boulder w/drill hole down 0.5' in good condition.