Certificate of Location of Government Corner

ID#: 622705 **Description:** SEC COR 27 28 33 34 62 **Date Set:** 6/30/1964 **County:** Olmsted

Section: 27 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1 1/2' south of centerline of CR 129, in centerline of old twp road north and 5' east of centerline of field entrance south
Top center cylinder shaped telephone pedestal NE 43.5'
Center orange and white pipeline marker NW 52.6'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes William Jones, 80.00 set post at corner to sect 27-28-33-34. Br. Oak 17 N82-1/2E 362. Br. Oak 10 S89E 358. Br. Oak 12 N54W 377.

5-1856 Thos Hunter P.6 No.9 shows sec corner 1/16 west 19.82 chs. M&L to 1/4 post. Meas 39.85 south to 1/4 post.

5-1856 Thos Hunter P.6 No.10 shows sec corner 1/16 east 19.94-1/2 chs M&L 2 BT's (N54-1/4° W 194 lks) and 53-1/4°W 70-1/2 lks). Meas north 39.80 chs to 1/4 post.

4-1863 P.C. Compton P.68 No.96 shows sec corner used to set 1/4 corner 27-34 M&L also shown in P.69 No.97 for sec 28.

5-1896 Hunter P.600 No.545 S.28'. W. Busian, no B trees but found stone in center road avered by Mr. H. Bear as set at spot of original stake. Cottonwood B tree taken. Meas north 39.93-1/2 N1/2°W 2635.71' to 1/4 corner boulder set M&L.

5-1902 W. Fraser P.14B S.26-27 found stone and B tree by Hunter. Meas east 39.89' to stone set M&L 2632.74'.

7-1939 J. Kerr P.488B town board found stone, took references NW corner entry stone school SW 18675 center 20" pine SE 89.0'

6-30-1964 J. Kerr found limestone monument and set permanent marker of a Cast Iron Monument above limestone.

6-7&8-1973 County Surveyor ran and meas line east to 1/16 stone found east of 1/4 27-34 R2632.74 M&L 1/16 1316.37 M&L east found meas 1316.22' x 3' or 2632.44' see 1/4 27-34. Ran and meas line north, found 21-22-27-28 not correct. Dug in blacktop found drill hole in boulder 3.1' N .3' W of iron, reset 1/4 27-28 true M&L (now close) at meas 2636.36'.

5-30-2001 Roger Brand found CIM in good condition 0.9' deep in road.

4-20-2009 County Surveyor found CIM down 1' in good condition.