Certificate of Location of Government Corner

ID#: 622706 **Description:** 1/4 SEC COR 27 28 62 **Date Set:** 6/8/1973 **County:** Olmsted

Section: 27 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2' north of north FAI-90 R/W fence and in centerline of old road bed north
3/4" rod in concrete in Minnesota Highway Disk RP marker NW 49.85'
3/4" rod in concrete in Minnesota Highway Department RP marker NE 50.35'
Minnesota Highway Department benchmark E 70.14'
County highway disk in NE side 6" cedar post NW 58.43'
Center RR spike in PP #40390 WNW 35.65'
Post w/sign 1 1/2' south
This corner is located by GPS reference stations "Munroe A & B"

Corner History:

1853 Gov't Notes North between sections 27 and 28. 40.00 chs. Set post at quarter section corner. Burr Oak 6 in. S10ºE 54 lks. Burr Oak 6 in. S25 1/2ºW 54 lks.

5-1856 Thos Hunter P.6 No.10 shows 1/4 post. 1/16 east 19.99 chs M&L, 2 BT's (N 49-3/4° E 405 lks) and (N 31-3/4° W 324 lks). 1/16 north 19.91 chs M&L, 2 BT's (S 57-3/4° E 441 lks) and S 51-1/2° W 329 lks). Meas south 39.80 chs to sec corner.

4-1863 P.C. Compton P.69 No.97 shows 1/4 stake used to set center sec 28.

5-1896 Thomas Hunter (P. 600 No. 545), County Surveyor, states corner and bearing trees gone. Reset a boulder, 10" x 12" x 18" midway and on line.

5-1902 William Fraser (P. 14 Book B), County Surveyor, found boulder.

7-1939 John Kerr (P. 488 Book B), County Surveyor, found boulder.

7-30-1968 J. Kerr found iron checked references. New RP's: Minn Hwy Dept elevation bench center E 69.73'. NW disc on NE side new 6" cedar corner post 58.5'.

6-8-1973 County Surveyor found iron rod set over boulder by M.H.D. in constructing I-90. Reset CIM over iron rod.

5-30-2001 Roger Brand found CIM in good condition.

4-9-2009 County Surveyor found CIM at surface in good condition.