Certificate of Location of Government Corner

ID#: 622709 **Description:** SEC CEN 27 62 **Date Set:** 6/7/1973 **County:** Olmsted

Section: 27 **Township:** 106N **Range:** 12W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
120d spike

Reference Ties:

The corner falls 93' north of centerline of WBL of FAI-90
This corner is located by GPS measurement

Corner History:

5-16-1856 Thos Hunter P.6 No.10 shows center sec with 2 bearing trees N 76-1/4°W 297 links and N 7-3/4°W 164 links. 1/16 west 19.99 chs M&L two BT's N 49-3/4°E 405 lks and N 31-3/4°W 324 links. 1/16 north 19.94 chs M&L two BT's N50-3/4E 127 links and N25-1/4°W 55 links. Meas south 39.76 chs to 1/4 post. N-S 1/16 line in SW 1/4 meas 39.84 chs. E-W 1/16 line in NW 1/4 meas 39.83 chs.

5-1902 W. Fraser P.14B set stone 2x10x24 at inters lines of all 1/4 corners. 1/16 north set stone 6x6x18 M&L 19.94 1316.04. 1/16 east set boulder M&L 19.94-1/2 1316.37. 1/16 south set boulder M&L 19.94 1316.04. 1/16 center SE 1/4 27 set boulder inters lines No meas.

6-5-1973 County Surveyor found pointed boulder in real wet soil and brush, this corner could shift E or W to align line if needed 4.15' E to bottom wire of woven wire. 5.5' SE to wired up corner post. Corner stone in fair line main fence running E.

6-7-1973 County Surveyor found 1/4 22-27 and 1/16 stones N and S if once set center 27 now removed in I-90 construction. Dug large area in I-90 RW for above stone and found everything removed and filled with huge limestones and then recovered with thin layer of black dirt. Entire N-S line on 45' offset west direct from both 1/16 stones boulders in wet virgin areas and adjustments to meet 45.66' meas at 1/4 22-27 would change very little the original offsets all on stones found. Set 120d as center 27 by meas line and meas from computed figures. 1/16 corner south or M&L between center 27 and 1/4 27-34 record a boulder set 5-1902 by W. Fraser P.14B 1316.04.

4-29-2009 County Surveyor found 120d spike down 0.1' in good condition.