Certificate of Location of Government Corner

ID#: 622905 **Description:** SEC COR 29 30 31 32 62 **Date Set:** 4/23/1997 **County:** Olmsted

Section: 29 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in centerline of CSAH 19 and 1 1/2' north of centerline of twp road west
Plastic disk in SW side PP #46247 SE 59.53'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor set post at corner to sections 29, 30, 31, and 32. 80 chs. Erected mound with trench and pits.

5-1890 Thomas Fraser, County Surveyor, (P 422 No. 428) found corner stake, but bearing trees disagreed. Measured NE 30 to SE 31 (159.7025 chains) and N 1/4 31 to N 1/4 33 (159.585 chains). Established corner at proportioned distances and set 3" x 8/15" x 24" stone.

7-1979 John Kerr for Town Board (P. 488B), found Limestone.

11-1961 M.H.D. found boulder with 3/4" Pipe and Bolt on top, East side of road.

7-12-1965 John Kerr, County Surveyor, found Limestone and Bridge Bolt Riser. Set Cast Iron Monument over the same. Measured SE 30 to S 1/4 30, 2636' and S 1/4 30 to SW 30, 2571.0'.

5-14-1979 County Surveyor took additional reference ties for road grading.

4-23-1997 Gerald Stephas, MN/DOT Survey Crew Chief, found spike down 0.6', Rebar down 1.2', Nail and Cap down 1.4', and CIM down 33". Removed Spike, Rebar, Nail and Cap. Set Olmsted County Cast Iron Monument over old CIM, updated the topography and measured new reference ties.

For details and survey analysis, contact the Minnesota Department of Transportation Surveys Office in Rochester, Minnesota.

4-3-2009 County Surveyor found CIM down 0.2' in good condition.