Certificate of Location of Government Corner

ID#: 623006 **Description:** W 1/4 SEC COR 30 62 **Date Set:** 10/3/2006 **County:** Olmsted

Section: 30 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1 1/2' north of north FAI-90 R/W fence
Post w/sign 1 1/2' south
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: Ball, Deputy surveyor. North between 25 and 30. 27.21 Br. Oak 10 in. 40.00 set quarter post. Br. Oak 10 in N87W 39 lks. Br. Oak 12 in S81E 62 lks.

6-1877 T. Hunter P.318 No.312 found original corner standing by fence tested by B trees stumps and proven correct. Set stone in place of stake. Meas north 39.97 to stone set from stake remains.

3-1878 T. Hunter P.332 No.326 found stone P.318 tested B tree stumps. 1/16 east set stake at 18.80-1/2 then 19.93-1/2 to center S89° 5' E this meas arrived at by proportions on mean of govt meas of north and south sides of W 1/2 30 38.75 south 38.99 north the govt mean is 13 lks short of actual measure. 1/16 north set stake or corner 19.97 M&L N1/2°W.

11-1961 Loren DaVal Minn Hwy Dept. found flat stone in fence line. Lines E-W-N-S fences corner lies 328.0 south of fence corner.

6-4-1968 J. Kerr found stone under N-S fence just .6' ± northwest of permanent highway marker. Corner really is about 320.0' south of random fence north as it runs west. Another highway marker lies 60' north. Set CIM on top of stone, top slightly above ground.

10-2-2006 County Surveyor found CIM up 0.2' broken and leaning.

10-3-2006 County Surveyor removed broken CIM and found flat topped stone down 0.6' in good condition. Removed stone and set 5' telspar pipe w/cast iron cap down 0.3'. Set post w/sign.