Certificate of Location of Government Corner

ID#: 623104 **Description:** S 1/4 SEC COR 31 62 **Date Set:** 7/15/2009 **County:** Olmsted

Section: 31 **Township:** 106N **Range:** 12W **Monument Description:** 1" copper plug w/punch mark RLS #42638

Reference Ties:

The corner falls 6 1/2' north of centerline of TH 52, 24 1/2' west of centerline of field drive south and in line with fence north
County Survey Disk in PP #16460 NW 47.18'
R/W monument S 56.58'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor West between sections 6 and 31. 40.00 chs. Set post and drove charred stake. Built mound with trench and planted osage orange seed SE and apple seek NE 79.20 chs. to township corner.

7-1876 Thomas Hunter, County Surveyor, (P. 302 No. 279) states that the corner was missing, but on the sworn testimony of a Mr. John Campion that the original corner came exactly between 2 fence posts on opposite sides of the road, set a temporary point there for the line south.

6-1890 Thomas Fraser, County Surveyor, (P. 442 No. 428) states that the corner was gone, but found the same posts as P. 302. Set a stone 21/2"x12"x17" between the posts which brings the corner 11/2 rods South of a straight line between the section corners of which the settlers had long been aware. Set two stones at the 1/16th East midway and on line.

4-20-1977 County Surveyor dug with the backhoe along the North edge of pavement of TH 52 at the 1/16th East. Found 2 stones as recorded by Fraser. Doubled the line and measure from S. Sec. corner-32 over the 1/16th West as found. The point came about 31/2' South of the North edge of the pavement. Dug down at the pavements edge and probed under the pavement, but could not find anything. Set a P.K. nail at this location in the pavement as the corner.

4-12-1999 County Surveyor set survey marker nail.

10-9-2003 County Surveyor found survey marker nail with head broken off. Base still in blacktop and in good condition.

10-14-2004 County Surveyor found survey marker nail with head broken off.

7-15-2009 County Surveyor found survey marker nail with head broken off at surface in good condition. Removed nail and set 1" copper plug w/punch mark in concrete down 0.3'.