Certificate of Location of Government Corner

ID#: 623105 **Description:** SW SEC COR 31 62 **Date Set:** **County:** Olmsted

Section: 31 **Township:** 106N **Range:** 12W **Monument Description:** Brass plug in concrete

Reference Ties:

The corner falls 9.4' north of centerline of T.H. 52 and 188' west centerline field drive north
Bottle cap in S side PP #16451 NE 102.52'
Ref pipe S 62.10'
This corner is located by GPS reference stations "JJS & JJS B"

Corner History:

1853 Gov't Notes Ball, Deputy Surveyor North between sections 1 and 6. 80.00 chs. Set post and drove charred stake. Built mound with trench and planted osage orange S.E. and apple seed N.E.

1875 State law required that monuments be set at township corners. Thomas Hunter, County Surveyor, placed stone monuments as required.

7-1876 Thomas Hunter (p. 302 No. 297), County Surveyor, found stake in the center of the road.

5-1880 John Fraser (P. 365 No. 356), County Surveyor, found monument set by Hunter.

5-1890 Thomas Fraser (P. 442 No. 428), County Surveyor, found engraved township corner set by Hunter. Co. Hwy. Dept. (B. 88) had flat limestone with oak stake on top.

1938 B.96 P.4 county highway department found brass plug on N edge pavement did not dig up corner 9.9' N of centerline. Notes say 7' N used plug meas west 2637.5' mark in line fence south.

6-30-1969 John Kerr, County Surveyor, found square stone centered below brass plug 20" below bottom of pavement. Wedged C.I.M. between stone and bottom of pavement of Hwy. 52.

4-8-1999 County Surveyor found brass plug in concrete down 0.3' in good condition.

10-19-2004 County Surveyor found brass plug down 0.3' in good condition.