Certificate of Location of Government Corner

ID#: 623206 **Description:** 1/4 SEC COR 31 32 62 **Date Set:** 10/19/2004 **County:** Olmsted

Section: 32 **Township:** 106N **Range:** 12W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 19, in centerline of twp road east and 2' south of centerline of twp road west
County Survey Disk in SE side PP #43091 SW 57.24'
County Survey Disk in NW side PP #42174 NE 60.40'
Bolt in punch hole in W end 18" CMP ENE 108.76'
1/2" iron 0.7' N of survey marker sign post ESE 112.11'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 31 and 32. 40.00 chs. Set a post at the quarter section corner. Deposited handful charcoal. Made mound, trench, and pits and planted cherry seeds NE and SW.

5-1890 Thomas Fraser, County Surveyor, (Book A P. 442 No. 428) could not find this corner. Set a stone 3" x 7" x 17" midway and on line between the section corners.

6-28-1968 John Kerr found the stone (Cert. Filed). Set the stone lower with a sash weight alongside and set a CIM over all.

6-27-1978 County Surveyor set a 10" C.I.M. over the CIM in place (the top of the CIM in place was broken off, so removed it). Took new reference points.

5-14-1979 County Surveyor took additional RP's for road grading 1/2"x22" iron .7 north of survey marker sign ESE 112.11'. Bolt through punch hole in west end 18" CMP in field drive ENE 108.76 on N side of road east.

1-1992 Brand and assoc. set RR spike from 1979. RP's and measure south corner (CIM) probably 2' deep and ground frozen.

10-18-2004 County Surveyor found R.R. spike down 0.2' in good condition. Took local ties and removed. Found CIM down 1.8' in good condition. Filled back in with gravel and blacktop.

10-19-2004 County Surveyor set 1" square pipe w/cap at surface from local ties at CIM location.

4-2-2009 County Surveyor found 1" square pipe w/cap at surface in good condition.