Certificate of Location of Government Corner

ID#: 623405 **Description:** S SEC COR 33 34 62 **Date Set:** 6/1/2009 **County:** Olmsted

Section: 34 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.6'
The corner falls 4' west of centerline of twp road north, 18' north of centerline of crooked twp road west and 24' SE of centerline of twp road on curve
County Survey Disk in NW side PP NE 30.01'
Bottle cap in SW side PP #16624 WNW 52.67'
GPS station Hanson (Cast Iron Cap on telspar pipe) SSE 33.1'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor West between sections 3 and 34. 80.00 chs. Set post and drove charred stake. Built mound with trench planted osage orange SE and apple seed NE.

8-18-1856 Thomas Hunter (P. 16 No. 25), County Surveyor, used corner and measured north and west.

6-5-1973 County Surveyor dug and found a 4" diameter dark spot in the subsoil fitting the lines of occupation and rows of trees. Accepted as corner and drove a railroad spike in spot and set a CIM over it.

10-31-1994 County Surveyor found CIM in good condition.

12-10-1998 County Surveyor found CIM in good condition.

5-4-2009 County Surveyor found CIM down 1.4' in good condition.

6-1-2009 County Surveyor removed CIM and found RR spike down 3.2' in good condition. Removed RR spike and set 5' telspar pipe w/Cast Iron Cap down 0.6' at CIM position.

9-21-2011 County survey crew found cast iron cap in good condition