Certificate of Location of Government Corner

ID#: 623504 **Description:** S 1/4 SEC COR 35 62 **Date Set:** 4/28/1981 **County:** Olmsted

Section: 02 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 12' south of E-W fence on S side of road
Post w/sign 1 1/2' south
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor West between sections 2 and 35. 40.00 chs. Set post for 1/4 S corner Burr Oak 8 in. N32ºW 186 lks. Burr Oak 7 in. S8ºW 36 lks.

4-1863 P.C. Compton, Surveyor, used this corner, a stake shown on plat, to set the Center Section 35 at intersecting 1/4 lines.

3-1935 county highway department (C.H.D. Book 53, P. 69) set a stone here on line and double the measure from the N 1/4 corner 35 (found) over the Center 35 (found).

4-28-1981 County Surveyor set a telspar pipe with Cast Iron Cap as the corner at the intersection of the line from the N 1/4 corner 35 (found 1975) over the Center 35 (found 1975) and the line from the S 1/4 corner 36 (set 1975) to S Sec. corner 34-35.

4-27-2009 County Surveyor found cast iron cap on telspar pipe at surface in good condition.