Certificate of Location of Government Corner

ID#: 623509 **Description:** SEC CEN 35 62 **Date Set:** 10/9/1975 **County:** Olmsted

Section: 35 **Township:** 106N **Range:** 12W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
60d spike

Reference Ties:

The corner falls 7' north of centerline of E-W twp road
This corner is located by GPS measurement

Corner History:

4-9-1863 P.C. Compton P.68 No.96 set center 35 at intersecting line for breakdown of NW 1/4 sec 35.

3-8-1935 A. Armstrong for county highway department book #53 Page 69 found 4x10x12 limestone with glass around it dist north to 1/4 corner 26-35=2648.0.

10-7-1975 County Surveyor dug with tractor 6' N-S x 8' E-W in line with fence north but on N edge E-W crushed road as line from W 1/4 corner to centerline road at E 1/4 corner fell on N edge Rd ± 10' no centerline. Bed rock about 2' deep and not much evidence of road bed below present road did not find anything. Corner will have to be set by intersecting 1/4 lines. After finding pointed boulder with wood stake on S side and broken crockery on W side of boulder at 1/16 corner west we dug again.

10-8-1975 County Surveyor at 1/16th west dug with backhoe on N side E-W road, found boulder stone with stake on S side and reinforcing rod at surface but not over stone (pottery around stone). Stone 3-1/2' N of centerline and 1/2' E of fence N. Set rod back over all.

10-9-1975 County Surveyor at this center 35 and found small piece of limestone standing on edge with glass around bottom of limestone (stone about 1-1/2"x8"x8" possibly broken off) only about 2-1/2' deep in road ± 6' N of centerline. This stone would be close to a straight line from W 1/4 35 over 1/16 boulder and within 1' of being double the distance. However this might have been set from W 1/4 corner 35 at 2640' since it is every fence to north we probably should honor it and set S 1/4 corner 35 using it and N 1/4 corner as found.

4-27-1981 County Surveyor at 1/16th east dug on line from W 1/4 corner 35 over the center 35 (spike over corner found 1975). Dug from 3' west of fence south (came 1285± from center 35) to 15' east of the fence south to reach midway from center 35 to nail set in appx center road north at 1/4 corner 35-36 in 1975. Dug 5' wide (ave) and 3' deep to clay but found nothing.

4-29-2009 County Surveyor found 60d spike set at stone location down 0.6' in good condition.