Certificate of Location of Government Corner

ID#: 623606 **Description:** 1/4 SEC COR 35 36 62 **Date Set:** 4/28/1981 **County:** Olmsted

Section: 36 **Township:** 106N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 6' south of centerline of E-W twp road, in centerline of field entrance north and in line with fence south
County Survey Disk in W side Fence post (end of fence north) NW 63.00'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor. North between sections 35 and 36. 40.00 chs. Set post at quarter section corner. Burr Oak 14 in. N66 E 227, Burr Oak 6 in. S471/2 W 340 links.

9-1856 E.P. Bircher, Surveyor, per T. Hunter, Deputy, (Old Road Book, Road No. 42) surveyed the road along the E-W 1/4 line of Section 35.

4-1863 P.C. Compton, Surveyor, (Book A, Page 68, No. 96) states that the post was removed. Established corner from witness trees. He used this corner to set the Center 35 at intersecting 1/4 lines and the 1/16 West of the Center midway between the Center and the West 1/4 corner 35, a stone set midway between the section corners in this survey.

5-1902 Will Fraser, County Surveyor, (Book B, Page 14) found a boulder on line of the section corners at 1/4 corner 34-35. Measured North 39.98 chs. and South 39.94 chs.

3-8-1935 A. Armstrong (C.H.D. Book 53, Page 14) found a 4" x 10" x 12" limestone with glass around the bottom at the Center 35.

10-1-1973 County Surveyor dug in the center of the E-W road and in line with the center of the road North but did not find anything at 1/4 corner 35-36.

11-21-1974 County Surveyor set 1/4 corner 34-35 on line between the section corners and at Will Fraser's prorated measure.

10-8-1975 County Surveyor dug at the Center 36, but did not find anything.

10-9-1975 County Surveyor dug at the 1/16 East of 1/4 corner 34-35 Found boulder and stake. Projected the line and doubled the distance from 1/4 corner 34-35 over the 1/16 East. Dug and found limestone and glass at the Center 35.

10-8 & 10-1975 County Surveyor dug again for 1/4 corner 35-36 but did not find anything.

4-28-1981 County Surveyor set a CIM over a 5/8" rod on the line from the W 1/4 corner 35 over the Center 35 and in line with the center of the road North.

4-27-2009 County Surveyor found CIM down 1' in good condition.