Certificate of Location of Government Corner

ID#: 630204 **Description:** 1/4 SEC COR 2 11 63 **Date Set:** 12/11/1981 **County:** Olmsted

Section: 02 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1' north of centerline of twp road east, 1' west of centerline of CR 119 north and 2 1/2' north of centerline of twp road west
County Survey Disk in W side PP #21349 SSE 24.34'
County Survey Disk in CP NE 66.63'
County Survey Disk in CP NW 62.10'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: William Jones, Deputy Surveyor West on true line between Sections 2-11. 39.93 1/2 chs. Set post at quarter section corner. Deposited charcoal and made mound, trench, and pits. Planted cherry seeds N.E. & S.W.

7-1873 Thomas Hunter, County Surveyor, (Old Field Book No. 3) used quarter post for the plat of Chester.

6-1885 Thomas Hunter, County Surveyor, (Old Field Book No. 14) found stake as set and found by me when survey of Chester was made.

9-1951 John Kerr, County Surveyor, (Field Book No. 52, Page 58) found stone at N.W. corner of block 2, Chester plat as set by T. Hunter.

8-1956 John Kerr, County Surveyor (Field Book No. 64, Page 47) used a spike at the quarter corner as point of beginning for a survey to the South.

8-1965 John Kerr, County Surveyor, set a Cast Iron Monument over a 120d spike. RPs-spike in pp SSE 24.42, Nw corner house SW 118.3, disc corner fence post NW 62.75, spike corner fence post NE 64.04.

5-26-1977 County Surveyor dug to verify Kerr's C.I.M. Found a shattered limestone (with pieces of brick and a drag tooth) over a stake hole (3' deep) 1.20 West and .65 South of Kerr's C.I.M. (removed). Set a 120d spike in the stake hole and a 1 1/4" x 16" pipe at the surface. Kerr's C.I.M. was not set over anything. RPs to pipe-county highway department disc in e side pp SSE 24.38, NW corner house SW 117.05, disc corner post NE 66.63, disc corner post NW 62.10. RPs to Kerr's CIM- county highway department disc in E side pp SSE 24.48, NW corner house SW 118.28, disc in corner post NE 65.35, disc in corner post NW 62.80.

12-11-1981 County Surveyor found 1 1/4" pipe set in 1977 bent East. Reset C.I.M. from the intersection of N.E. and N.W. R.P.'s. The disc in the power pole S.S.E. is chopped off but the nail on the East side (down low) was still there and checked O.K. The S.W.'ly tie to the house was .15 short but the corner of the house was covered and could be differenct. This is a correction of a corner. The correct corner is 1.20 West and .65 South of Kerr's C.I.M. (removed).

6-28-1982 County Surveyor NW corner Blk 2 Chester; Found a 3/4"x1' pipe with a 1/2"x3' rerod inside. Found limestone 2 1/2"x4"x10" standing .17 south and .20 west of the pipe and rod down 1'to1 1/2'. Stone may be broken remains of Hunter's stone. Replaced rod and pipe at former location. NE corne BLK 1 Chester- found 2" capped pipe. Removed pipe and reset.

8-18-2003 County Surveyor found CIM down 0.3' in good condition.