Certificate of Location of Government Corner

ID#: 630209 **Description:** SEC CEN 2 63 **Date Set:** 9/18/1995 **County:** Olmsted

Section: 02 **Township:** 106N **Range:** 13W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

1" square pipe w/cap RLS #15809

County Surveyor recommends using the monumented center of section.

Reference Ties:

The corner falls in centerline of CR 119 and in line with fence west
Ref pipe WSW 44.76'
This corner is located by GPS measurement

Corner History:

6-30-1857 John B. Fellows, (Book A, Page 26, Survey No. 42), used center section. No description of monument used.

7-28-1958 Ken McGhie found and used monument for the plat of Chester Heights.

8-21-1962 John Kerr, County Surveyor, (Kerr Field Book No. 85, Page 74), set 1/2" rod as center section 2. Corner accepted until porven otherwise.

8-2-1965 John Kerr, County Surveyor, set Cast Iron Monument over 6" bolt in rock base.

6-23-1972 P.E. Highum found and used monument.

5-26-1977 County Survey Crew dug on west side of Kerr's monument and found nothing.

7-16-1979 T. Taylor Co. found and used monument at center of section 2.

5-24-1990 Roger Brand & Associates found and used Cast Iron Monument.

12-9-1991 Roger Brand & Associates found and used Cast Iron Monument.

6-1995 County Highway Department found Cast Iron Monument in good condition. Set 1" square pipe w/cap as reference and referenced corner prior to cold recycling bituminous project. Removed monument.

9-18-1995 County Highway Department set 1" square pipe w/cap at surface at 1995 referenced location.

8-18-2003 County Survey Crew found 1" square pipe w/cap at surface in good condition and measured its position using GPS.

5-4-2011 Joel Thoreson, County Surveyor, recommends using the monumented center of section based on historical use of this position.

4-3-2015 County Survey Crew found 1" square pipe w/cap at surface in good condition and lowered monument prior to bituminous mill and overlay project (P391).