Certificate of Location of Government Corner

ID#: 630304 **Description:** 1/4 SEC COR 3 10 63 **Date Set:** 8/21/1963 **County:** Olmsted

Section: 03 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 22' west of centerline of waterway and in backyard of house #5473 Logan St SE
Post w/sign 2' east
This corner is located by GPS reference stations "Brentwood A & B"

Corner History:

1853 Gov't Notes William Jones Deputy Surveyor; 40.01-40.01 set post at 1/4 section corner. RPs- 13" burr oak 56°W 53 links, 7" burr oak N44°W 70 links.

10-1882 T. Hunter Pg.380 No.371; Found stone in center of road in line fence running south. Tested by stumps of SW bearing tree.

1929 Bk.1 Pg.37; found stone.

1939 J. Kerr Bk. 16 Pg.14, found stone

1946 J. Kerr Bk.30 Pg.76; found limestone with boulders on east side. Meas. E & W.

1953 J. Kerr Bk 58 Pg.50 found stone.

1959 J. Kerr Bk.75 Pg.44 found stone

8-21-1963 J. Kerr set CIM over stone. RPs-Tree SW 50.25', 6" Burr Oak in fence South 61.5', + in Metal Culvert West NW 28.82 ft.

11-4-1995 Roger Brand & Associates found and used monument in survey of W 1/2 Section 3.

9-25-2006 County Surveyor visited area of corner and found nothing. There is a N-S drainage ditch through the area. Found metal culvert WNW, but could not find "+".

8-7-2007 County Surveyor found CIM down 0.4' in good condition. Set post w/sign.

4-28-2009 County Surveyor found CIM down 0.4' in good condition.