Certificate of Location of Government Corner

ID#: 630305 **Description:** SEC COR 3 4 9 10 63 **Date Set:** 11/14/1994 **County:** Olmsted

Section: 03 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #42638

Reference Ties:

The monument is down 0.7'
The corner falls 1/2' east of centerline of CSAH 11 and 1' north of fence west
120d spike in 10" Burr Oak W 85.8'
County highway disk in PP SSW 102.28'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William A Jones Deputy Surveyor; Set post at corner to section 3-4-9-10. RPs- 13" burr oak N5°E 30 links, 11" burr oak N 12°W 175 links, 8" burr oak S32°W 113 links, 7" burr oak S53°E 76 links.

1937 County Highway Department Bk.88 Pg.73; Found stone.

1949 J. Kerr Bk.41 Pg.46; Took measurements.

1959 J. Kerr Bk.75 Pg.44; Stone and iron. Took measurements.

1962 County Highway Department Bk.274 Pg.3; Found boulder and 2" pipe. RPs- spike in fence post NNW 37.52', spike in clump of oaks ENE 51.08', spike & disc in twin oak NW 69.13'.

8-21-1963 J. Kerr set CIM over boulder. RPs- twin burr oak N52°30' W 69.0', 120d in 10" burr oak N90°W 85.8', disc in pp SSW 102.28', disc in top fence post W 34.9'.

5-17-1989 County Surveyor found RR spike in blacktop surface CR 11

5-19-1989 County Surveyor found CIM below RR spike in good condition

6-22-1994 County highway crew referenced CIM before cold recycling bituminous surface of CR 11

11-14-1994 County Highway Department set 1" square pipe with cap after road resurfaced.

12-4-2003 County survey crew found 1" square pipe w/cap at surface in good condition.

3-7-2012 County survey crew found 1" square pipe with cap at the surface in good condition. Lowered pipe and replaced cap in preparation for bituminous road overlay.