Certificate of Location of Government Corner

ID#: 630306 **Description:** 1/4 SEC COR 3 4 63 **Date Set:** 11/14/1994 **County:** Olmsted

Section: 03 **Township:** 106N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 11 and in line with E-W PP line
The monument is down 1'
County Survey Disk in PP #18924 E 30.25'
County Survey Disk in PP #19042 SE 76.08'
County Survey Disk in PP #40293 W 33.37'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Willima Jones; 39.12 set a post at 1/4 section post. RPs- 10" burr oak N32E 445, 12" burr oak S27E 478.

4-1878 T. Hunter, Pg.333 No.327; Corner gone, Found old post hole, but set no stake or stone.

1935 county highway department Bk.75 Pg.8; Found wooden stake with small boulders around it in center of road.

1949 J.Kerr; Ties to 1/16 north of 1/4 corner 3-4; 1" pipe set as 1/16. RPs- spud in west side pp SW 66.35', spud in south side telephone pole ENE 35.0', corner falls 35' north of fence to east.

1960 J. Kerr (Bk.78 Pg.65); Set 1/16 north with 1" pipe. RPs- spike on W S pp, SW 66.35, spike south side pp N of E 35.0. Ties to 1/4 corner 3-4; spike in pp NW 35.5, spike in center pier of RR bridge SW 149.9, centerline of RR tracks south 184.18'

8-16-1965 J. Kerr found 2" pipe over stone. Reset CIM. RPs-Spk and Disc in F.P. NW 59.32', Spk and Disc in Cor. F.P. W 51.1', Center line railroad tracks 228.7', Spk and Disc in brace pole SW 81.98', Spk and Disc in P.P. East 30.52, Spk and Disc in P.P. SE 76.04'.

11-22-1972 County Surveyor found and used CIM

8-29-1979 County Surveyor set C.I.M. over C.I.M. C.H. Disc in P.P. #19042 SE 76.08, County Surveyors disc in P.P. #18924 E 30.25, County Surveyor disc in P.P. #40293 W 33.37.

6-1980 County Surveyor found 1/16 north, 1" pipe.

12-11-1981 County Surveyor found C.I.M. tilted, removed and set 1" square pipe w/cap at road surface.

5-17-1989 County Surveyor found 1" square pipe w/cap in center line of C.R. # 11 in good condition.

6-1994 County Surveyor, pipe with cap referenced and removed before cold recycling bituminous surface of C.R. 11

11-14-1994 county highway department set 1" square pipe w/cap at surface from 1994 overlay tie out.

8-1996 Dean Strange, Peoples Coop found 2" disc in road surface.

12-1-2003 County Surveyor found 1" square pipe w/cap at surface in good condition.

5-20-2011 County survey crew found 1" sq. pipe with cap in good condition. Drove pipe down below bituminous in preparation for road surface milling and overlay.