Certificate of Location of Government Corner

ID#: 630404 **Description:** 1/4 SEC COR 4 9 63 **Date Set:** 10/3/2012 **County:** Olmsted

Section: 04 **Township:** 106N **Range:** 13W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The moument is up 0.2'
The corner falls on E side of CP to fences N-S-W
Post w/sign 2' east
This corner is located by GPS reference stations "Swanson A & B"

Corner History:

1853 Gov't Notes, William Jones, Deputy Surveyor; Set post at 1/4 section corner. RP- 11" burr oak N7°E 222 links. Made trench.

4-9-1875 T. Hunter (Book A, Pg.267 No.265) found small stake in road from marked bearing tree stump. Pg.333 No.327 Hunter found remains of stake.

1929 J.Kerr Bk.3 Pg.37; Ties to N 1/4 9- nail in 15: burr oak SW 31.61', nail in 15" burr oak NW 24.58'.

1938 J.Kerr Bk.12 Pg.62; Found stone. RPs- 15" burr oak NW 24.58', 15" burr oak SW 31.67'. Run & meas. Line west 2644.98'. Set axle shaft M & L 1322.49'. RPs- center steel fence post north 30.5', telephone pole NW 40.03'.

1949 J.Kerr Bk.41 Pg.46; Used corner. RPs- Oak NW 24.5', center 20" elm NE 74.2'

8-2-1965 J. Kerr found an iron bar set in concrete in place of limestone. Both reference points checked out with iron. Accepted and left as is.

4-31-1989 County Surveyor found 1/2" x 2" iron bar in concrete. Checked RP's 22" Oak (1965) is now 26" and ± 25' NW'ly 30" Elm (1965) now dead and ± 74 1/2' NE.

12-4-2003 County Surveyor found 1/2"x2" iron in concrete in good condition up 0.2'.

8-31-2011 County survey crew found 1/2"x2" iron bar in concrete in good condition.

10-3-2012 County survey crew found 1/2" x 2" x 2' iron bar in concrete in good condition. Removed and replaced with a cast iron cap on telspar pipe.